



Technical Service Bulletin

Technical Service Bulletin: tsb102921

Released Date: 23-Jun-2008

Camshaft Procedure, Remove Section Revision

Camshaft Procedure, Remove Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds a table, Camshaft Guide Installation Chart, to the Remove Section of the Camshaft procedure to show the correct c-clip positions for the camshaft removal tool.

Related Procedures

56-001-008-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-008-tr.html)

Camshaft
(/qs3/pubsys2/xml/en/procedures/56/56-001-008-tr.html)

Last Modified: 23-Jun-2008