



Technical Service Bulletin

Technical Service Bulletin: tsb102986

Released Date: 13-Aug-2008

Fleetguard™ Centrifuge Procedure, Assemble Section Revision

Fleetguard™ Centrifuge Procedure, Assemble Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Assemble section in Procedure 007-068 (Fleetguard™ Centrifuge) to include a new illustration and additional instructions to be used in the assembly process.

Related Procedures

102-007-068
(/qs3/pubsys2/xml/en/procedures/102/102-007-068.html)

Fleetguard® Centrifuge
(/qs3/pubsys2/xml/en/procedures/102/102-007-068.html)

Last Modified: 13-Aug-2008