



Technical Service Bulletin

Technical Service Bulletin: tsb103209

Released Date: 12-Dec-2008

Eliminator™ Filter Procedure, Assemble Section Revision

Eliminator™ Filter Procedure, Assemble Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic announces a revision to the Assemble Section of Procedure 007-067 (Eliminator™ Filter). The hydraulic motor mounting capscrew torque value has been revised.

Related Procedures

56-007-067-tr
(/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)

Eliminator™ Filter
(/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)

Last Modified: 12-Dec-2008