



Technical Service Bulletin

Technical Service Bulletin: tsb103222

Released Date: 20-Nov-2008

Aftercooler Assembly Procedure, Assemble Section Revisions

Aftercooler Assembly Procedure, Assemble Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic announces revisions to the Assemble section of Procedure 010-002 (Aftercooler Assembly).

The revisions clarify the Assemble section of the procedure by removing information about the installation of the lower cooler element gasket.

Only one gasket is used; between the aftercooler support and aftercooler cover.

Related Procedures

56-010-002-tr
(/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)

Aftercooler Assembly
(/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)

Last Modified: 20-Nov-2008