



Technical Service Bulletin

Technical Service Bulletin: tsb103512

Released Date: 14-May-2009

Coolant Thermostat Procedure, Install Section Revisions

Coolant Thermostat Procedure, Install Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the installation torque value for the new QSK60 thermostat clamping plates and cover plates. This is the same thermostat housing used on the QSK60 with electronically actuated injectors.

Related Procedures

56-008-013-tr
(/qs3/pubsys2/xml/en/procedures/56/56-008-013-tr.html)

Coolant Thermostat
(/qs3/pubsys2/xml/en/procedures/56/56-008-013-tr.html)

Last Modified: 14-May-2009