



Technical Service Bulletin

Technical Service Bulletin: tsb103852

Released Date: 15-Jun-2009

(Bearings, Connecting Rod) Procedure, Connecting Rod Bearing Thickness Specification Revisions

(Bearings, Connecting Rod) Procedure, Connecting Rod Bearing Thickness Specification Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Clean and Inspect for Reuse section of Procedure 001-005 (Bearings, Connecting Rod) to reflect the different connecting rod bearing thickness specifications for the new and old bearings.

Related Procedures

56-001-005-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-005-tr.html)

Bearings, Connecting Rod
(/qs3/pubsys2/xml/en/procedures/56/56-001-005-tr.html)

Last Modified: 15-Jun-2009