



Technical Service Bulletin

Technical Service Bulletin: tsb103922

Released Date: 21-Sep-2009

Eliminator™ Filter Procedure, Remove and Install Section Revisions

Eliminator™ Filter Procedure, Remove and Install Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-067 (Eliminator™ Filter) in Section 7 of the QSK45 and QSK60 Service Manual, Bulletin 4021530. The changes to the Remove and Install sections are the result of a design change to the Eliminator™ filter mounting bracket.

Note : This is a product improvement and not subject to campaign.

Related Procedures

56-007-067-tr
(/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)

Eliminator™ Filter
(/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)

Last Modified: 21-Sep-2009