



Technical Service Bulletin

Technical Service Bulletin: tsb103923

Released Date: 18-Sep-2009

Fuel Filter Head Procedure, Multiple Section Revisions

Fuel Filter Head Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Disassemble and Assemble Sections of Procedure 006-017 (Fuel Filter Head) in Section 6 of the QSK45 and QSK60 Series Service Manual, Bulletin 4021530.

Removal specifications and torque specifications for the fuel filter head adapter spuds and adapter rings have been added.

Related Procedures

56-006-017-tr
(/qs3/pubsys2/xml/en/procedures/56/56-006-017-tr.html)

Fuel Filter Head
(/qs3/pubsys2/xml/en/procedures/56/56-006-017-tr.html)

Last Modified: 18-Sep-2009