



Technical Service Bulletin

Technical Service Bulletin: tsb103935

Released Date: 21-Aug-2009

(Fan Hub, Belt Driven) Procedure, Inspect for Reuse and Assemble Section Revisions

(Fan Hub, Belt Driven) Procedure, Inspect for Reuse and Assemble Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Inspect for Reuse and Assemble sections of Procedure 008-036 (Fan Hub, Belt Driven). The revisions include addition of the fan hub end clearance specification and information reflective to lubrication of the fan hub (if applicable).

This is a product improvement and **not** subject to campaign.

Related Procedures

56-008-036-tr
(/qs3/pubsys2/xml/en/procedures/56/56-008-036-tr.html)

Fan Hub, Belt Driven
(/qs3/pubsys2/xml/en/procedures/56/56-008-036-tr.html)

Last Modified: 21-Aug-2009