



Technical Service Bulletin

Technical Service Bulletin: tsb104036

Released Date: 29-Jan-2010

Pre-Lubricating Oil Pump Procedure, Major Revision

Pre-Lubricating Oil Pump Procedure, Major Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-063 (Pre-Lubricating Oil Pump) adding information about the "Compact" Prelub™ Pump and the "High Volume" Prelub™ Pump. This major revision affects all sections of this procedure.

Related Procedures

56-007-063-tr
(/qs3/pubsys2/xml/en/procedures/56/56-007-063-tr.html)

Pre-Lubricating Oil Pump
(/qs3/pubsys2/xml/en/procedures/56/56-007-063-tr.html)

Last Modified: 29-Jan-2010