



Technical Service Bulletin

Technical Service Bulletin: TSB110300

Released Date: 16-Jul-2012

New Copper Seal for HPI Injectors in High Horsepower Engines

New Copper Seal for HPI Injectors in High Horsepower Engines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces a new copper seal for use with HPI injectors in High Horsepower engines.

The new seal is the same size as the old seal. The new part has modified internal geometry and a revised material specification to improve durability.

Injector Copper Seal Part Numbers

New Part Number	Old Part Number
4307148	3867687

Injector Copper Seal Part Numbers

Size	New Part Number	Old Part Number
Oversize 1.27 mm [0.05 in]	4307149	3347933
Oversize 2.54 mm [0.10 in]	4307150	3347934
Oversize 3.81 mm [0.15 in]	4307151	3347935

The new seals have been installed on new engines starting with engine serial number (ESN) first 66301859 at the Daventry Engine Plant.

The old seal has **not** been obsoleted and will continue to be available for service use on the Heavy Duty engines.

Document History

Date	Details
2011-11-1	Module Created

Date	Details
2011-11-15	QSOL Quick Fix Reason: Spelling Error Notes: none
2012-7-11	information about oversize parts availability for service use was omitted. This updtae is to make this information available for the field

Last Modified: 16-Jul-2012
