



Technical Service Bulletin

Technical Service Bulletin: TSB120070

Released Date: 03-Mar-2013

New Fuel Pump for QSK23, QSK45, QSK60, and QSK78 Engines

New Fuel Pump for QSK23, QSK45, QSK60, and QSK78 Engines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces a new fuel pump for use on QSK23, QSK45, QSK60, and QSK78 industrial engines.

The new pump is a modified design. It has modified internal pump body geometry that allows installation of the seal retainer to improve pump durability.

The new pump is compatible for installation with the old pump.

Fuel Pump Part Numbers

Engine Family	Old Part Number			New Part Number		
	Pump, Fuel (Gear Pump)	Pump, Fuel (Mid Assembly)	Pump Fuel (Complete Assembly)	Pump Fuel (Gear Pump)	Pump, Fuel (Mid Assembly)	Pump, Fuel (Complete Assembly)
QSK23	4903531	4062160	4087997	2897672	4307238	4307242
QSK45	4903530	4921680	4088185	2897670	4307239	4307243
QSK60	4903532	4062159	4088186	2897671	4307240	4307244
QSK78	4903534	4010665	4088188	2897673	4307241	4307245

The new pumps have been installed on new engines, starting with engine serial number (ESN) first 33192035 for QSK45 and QSK60 and ESN first 66302303 for QSK78, at the Daventry Engine Plant. The old pump has **not** been obsoleted and will continue to be available for service use on power generation engines.

Document History

Date	Details
2012-3-6	Module Created
2013-2-12	Spelling Error

Last Modified: 03-Mar-2013
