



Technical Service Bulletin

Technical Service Bulletin: TSB120295

Released Date: 13-Jan-2014

New Top Piston Ring for QSK45 and QSK60 HPI

New Top Piston Ring for QSK45 and QSK60 HPI

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of a new top piston ring for all QSK45 and QSK60 HPI engines. The new top piston ring combines features from the current Tier 1 and Tier 2 style top piston rings. The new hybrid ring has the Tier 1 ring base geometry, combined with the three degree cutback on the top edge from the Tier 2 ring.

The new piston ring is Part Number 3647001. It supersedes piston ring, Part Number 4910251.

The engine serial number (ESN) first for a production engine with the new piston ring is 33196060, built on 26 November 2012.

The new ring, Part Number 3647001, is included in the Piston Ring Set, Part Number 4309254, and in the Engine Piston Kit Part Number 4309253.

Table 1: Piston Ring Set - Part Number 4309254

Part Number	Part Name	Quantity
3090450	Piston Ring, Oil	1
3645611	Piston Ring, Compression	1
3647001	Piston Ring, Compression	1

Document History

Date	Details
2012-11-25	Module Created
2014-1-2	none

