



Technical Service Bulletin: TSB210043

Released Date: 21-Mar-2024

New Cylinder Head with Improved Casting

New Cylinder Head with Improved Casting

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM500
- QSK60 CM500 M
- QSK60 CM500 G
- QSK60 CM850
- QSK60 CM850 M
- QSK60 CM850 G
- QSK60 CM2150 MCRS
- QSK60 CM2150 MCRS M
- QSK60 CM2150 MCRS G
- QSK60 CM2350 MCRS
- QSK60 CM2350 MCRS M
- QSK60 CM2350 MCRS G

Description of Change

The cylinder head casting has been modified. This change increases the thickness of the wall casting in between the lower water jacket and intake port. This improves the strength of the cylinder head in this area preventing cracks and coolant entry to the intake port.

Reason for Change

There have been reports of coolant in the intake port during engine operation. Following investigation, cracks are found in the casting.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Cylinder Head	5371844	Yes	Yes	5538438
Cylinder Head	5374754	Yes	Yes	5538439
Cylinder Head	5372057	Yes	Yes	5538441
Cylinder Head	4382239	Yes	Yes	5540562

Part Compatibility

- Parts are compatible with all style cylinder blocks and cylinder head gaskets. If all cylinder heads are being replaced on the engine, they **must** all be the new part number.
- If a single existing part number cylinder head malfunctions during operation, the single cylinder head can be replaced with a new part number.

Part Inventory Action

Use existing part number inventory before using the new part number.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information			
Cylinder Head Part Number	ESN First	Build Date ¹	Plant
5538438	33223509	15 December 2020	Daventry
5538439	33223429	2 December 2020	Daventry
5538441	33223501	14 December 2020	Daventry
5540562	33224444	01 April 2021	Daventry

Document History

Date	Details
2021-2-18	Module Created
2021-5-19	Updated Table 1 and Table 2.
2024-3-19	Updated Product Affected.