

Manual Change History (5659673) QSK60 CM2150 MCRS Fault Code Troubleshooting Manual Change History

Date	01-Mar-2026
Fault Code / Symptom	Engine Crankshaft Speed/Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004053
Solution Title	Crankshaft/camshaft tone wheel
Update Reason	Solution Removed

Date	01-Mar-2026
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00004053
Solution Title	Crankshaft/camshaft tone wheel
Update Reason	Solution Removed

Date	18-Jan-2026
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed

Date	18-Jan-2026
Fault Code / Symptom	Intake Manifold 2 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed

Date	18-Jan-2026
Fault Code / Symptom	Intake Manifold 2 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed

Date	18-Jan-2026
Fault Code / Symptom	Intake Manifold 3 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed

Date	18-Jan-2026
Fault Code / Symptom	Intake Manifold 4 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed

Date	14-Dec-2025
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00002816
Solution Title	Turbocharger oil seal is leaking air into crankcase
Update Reason	Solution Reordered

Date	14-Dec-2025
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00002816
Solution Title	Turbocharger oil seal is leaking air into crankcase
Update Reason	Solution Modified

Date	14-Dec-2025
Fault Code / Symptom	High Blowby
Solution Number	S00002816
Solution Title	Turbocharger oil seal is leaking air into crankcase
Update Reason	Solution Reordered
Date	14-Dec-2025
Fault Code / Symptom	High Blowby
Solution Number	S00002816
Solution Title	Turbocharger oil seal is leaking air into crankcase
Update Reason	Solution Modified
Date	07-Dec-2025
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00004024
Solution Title	Lubricating oil cooler element is malfunctioning or restricted
Update Reason	Solution Reordered
Date	07-Dec-2025
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00004024
Solution Title	Lubricating oil cooler element is malfunctioning or restricted
Update Reason	Solution Modified
Date	16-Nov-2025
Fault Code / Symptom	External Fuel Leak
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	26-Oct-2025
Fault Code / Symptom	Droop Adjust Potentiometer Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	26-Oct-2025
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00000553
Solution Title	Verify performance complaint
Update Reason	Solution Removed
Date	26-Oct-2025
Fault Code / Symptom	Droop Adjust Potentiometer Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010055
Solution Title	Droop adjust potentiometer voltage check
Update Reason	Solution Removed
Date	26-Oct-2025
Fault Code / Symptom	Droop Adjust Potentiometer Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010880
Solution Title	Droop adjust potentiometer circuit check
Update Reason	Solution Removed
Date	26-Oct-2025
Fault Code / Symptom	Droop Adjust Potentiometer Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010057
Solution Title	Droop adjust potentiometer circuit pin to pin short
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00012542
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00012542
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 2 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 2 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 2 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 3 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 3 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 3 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 4 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 4 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 4 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 2 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 2 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 2 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 3 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 3 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 3 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 4 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 4 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 4 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012517
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012491
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Added
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012493
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Added
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012492
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Added
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000653
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Removed

Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000673
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Removed
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000652
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Removed
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012491
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Added
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012493
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Added
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012492
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Added

Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000653
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Removed
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000673
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Removed
Date	27-Jul-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000652
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Removed
Date	21-Jul-2025
Fault Code / Symptom	External Lubricating Oil Leak
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added
Date	21-Jul-2025
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added
Date	21-Jul-2025
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added

Date	01-Jun-2025
Fault Code / Symptom	Engine Fuel Pump Intake Oil Pressure - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Jun-2025
Fault Code / Symptom	Engine Fuel Pump Intake Oil Pressure - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Jun-2025
Fault Code / Symptom	Engine Fuel Pump Intake Oil Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Jun-2025
Fault Code / Symptom	Engine Fuel Pump Intake Oil Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003211
Solution Title	OEM temperature sensor open circuit check
Update Reason	Solution Reordered

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003211
Solution Title	OEM temperature sensor open circuit check
Update Reason	Solution Modified

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Reordered

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Modified

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Reordered

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Reordered
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Reordered

Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Reordered
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 2 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003855
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Reordered

Date	26-May-2025
Fault Code / Symptom	Intake Manifold 2 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003855
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 2 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003855
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Reordered
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 2 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003855
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed

Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Modified

Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Modified
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 7 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 7 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 8 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver 8 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 10 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 10 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 11 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 11 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 12 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 12 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 13 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 13 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 14 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 14 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 15 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 15 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed

Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 16 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 16 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 9 Circuit - Current Below Normal or Open Circuit
Solution Number	S00012280
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Added
Date	18-Nov-2024
Fault Code / Symptom	Injector Solenoid Driver Cylinder 9 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000533
Solution Title	ECM fuel injector solenoid driver is malfunctioning
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005939
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005939
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Fuel Delivery Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005939
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Fuel Delivery Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Pre-Oil Filter Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005939
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Pre-Oil Filter Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Pre-Oil Filter Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005939
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Pre-Oil Filter Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Post-Oil Filter Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005939
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Post-Oil Filter Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Post-Oil Filter Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005939
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Post-Oil Filter Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005939
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005939
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	09-Sep-2024
Fault Code / Symptom	Auxiliary Pressure Sensor Input 1 - Special Instructions
Solution Number	S00003464
Solution Title	OEM pressure/temperature exceeded engine protection limits
Update Reason	Solution Removed
Date	26-Aug-2024
Fault Code / Symptom	High Blowby
Solution Number	S00003916
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	26-Aug-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	19-Aug-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00012091
Solution Title	Fuel level check
Update Reason	Solution Added
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold Pressure Bank Imbalance - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold Pressure Bank Imbalance - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Exhaust Gas Temperature Bank Imbalance - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Exhaust Gas Temperature Bank Imbalance - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered

Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	07-Apr-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011989
Solution Title	Fuel pump actuator is malfunctioning
Update Reason	Solution Added
Date	07-Apr-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000980
Solution Title	Fuel pump actuator is malfunctioning
Update Reason	Solution Removed
Date	07-Apr-2024
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001649
Solution Title	Electric fuel lift pump resistance check
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00001576
Solution Title	Cold weather starting aid malfunction
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00001576
Solution Title	Cold weather starting aid malfunction
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002009
Solution Title	Fuel pump actuator resistance check
Update Reason	Solution Removed

Date	17-Mar-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Reordered

Date	17-Mar-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 1 (A1) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 1 (A1) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 3 (A2) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 3 (A2) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 5 (A3) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 5 (A3) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 7 (A4) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 7 (A4) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 9 (A5) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 9 (A5) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 11 (A6) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 11 (A6) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 13 (A7) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 13 (A7) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 15 (A8) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 15 (A8) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 2 (B1) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 2 (B1) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 4 (B2) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 4 (B2) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 6 (B3) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 6 (B3) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 8 (B4) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 8 (B4) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 10 (B5) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 10 (B5) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 12 (B6) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 12 (B6) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 14 (B7) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 14 (B7) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 1 (A1) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 1 (A1) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 3 (A2) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 3 (A2) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 5 (A3) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 5 (A3) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 7 (A4) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 7 (A4) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 9 (A5) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 9 (A5) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 11 (A6) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 11 (A6) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 13 (A7) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 13 (A7) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 15 (A8) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 15 (A8) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 2 (B1) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 2 (B1) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 4 (B2) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 4 (B2) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 6 (B3) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 6 (B3) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 8 (B4) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 8 (B4) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 10 (B5) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 10 (B5) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 12 (B6) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 12 (B6) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 14 (B7) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 14 (B7) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 16 (B8) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 16 (B8) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010718
Solution Title	Exhaust gas temperature sensor converter is malfunctioning
Update Reason	Solution Added
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 1 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 3 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 5 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 7 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 9 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 11 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 13 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 15 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 2 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 4 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 6 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 8 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 10 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 12 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 14 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Deviation Low for Cylinder 16 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 3 (A2) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 4 (B2) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 11 (A6) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 5 (A3) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Lubricating Oil in the Coolant
Solution Number	S00001324
Solution Title	Transmission lubricating oil cooler is malfunctioning
Update Reason	Solution Removed
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 1 (A1) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 5 (A3) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 7 (A4) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 9 (A5) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 11 (A6) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 13 (A7) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 15 (A8) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 2 (B1) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 6 (B3) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 8 (B4) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 10 (B5) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 12 (B6) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 14 (B7) - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 1 (A1) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 3 (A2) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 5 (A3) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 7 (A4) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 9 (A5) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 13 (A7) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 15 (A8) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 2 (B1) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 4 (B2) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 6 (B3) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 8 (B4) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 10 (B5) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 12 (B6) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 14 (B7) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 16 (B8) - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 3 (A2) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 5 (A3) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 7 (A4) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 9 (A5) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 11 (A6) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 13 (A7) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 15 (A8) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 2 (B1) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 6 (B3) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 8 (B4) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 10 (B5) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 12 (B6) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 14 (B7) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 16 (B8) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 1 (A1) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Sensor Circuit Cylinder 4 (B2) - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 1 (A1) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 3 (A2) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 7 (A4) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 9 (A5) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 11 (A6) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 13 (A7) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 15 (A8) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 2 (B1) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 4 (B2) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 6 (B3) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 8 (B4) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 10 (B5) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 12 (B6) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 14 (B7) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Exhaust Gas Temperature Cylinder 16 (B8) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	24-Dec-2023
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000507
Solution Title	Fuel pump actuator circuit pin to ground short
Update Reason	Solution Removed
Date	12-Nov-2023
Fault Code / Symptom	Control Module Identification Input State Error - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004795
Solution Title	ECM identification input state error
Update Reason	Solution Reordered

Date	12-Nov-2023
Fault Code / Symptom	Control Module Identification Input State Error - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004795
Solution Title	ECM identification input state error
Update Reason	Solution Modified
Date	12-Nov-2023
Fault Code / Symptom	Control Module Identification Input State Error - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004795
Solution Title	ECM identification input state error
Update Reason	Solution Reordered
Date	12-Nov-2023
Fault Code / Symptom	Control Module Identification Input State Error - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004795
Solution Title	ECM identification input state error
Update Reason	Solution Modified
Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Reordered
Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Modified

Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Reordered

Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Modified

Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Reordered

Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Modified

Date	11-Jun-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	11-Jun-2023
Fault Code / Symptom	Electronic Calibration Code Incompatibility - Out of Calibration
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	30-Apr-2023
Fault Code / Symptom	Electronic Calibration Code Incompatibility - Out of Calibration
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Modified
Date	26-Mar-2023
Fault Code / Symptom	High Blowby
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed

Date	26-Mar-2023
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00011256
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000362
Solution Title	Lubricating oil temperature sensor resistance check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000362
Solution Title	Lubricating oil temperature sensor resistance check
Update Reason	Solution Removed
Date	15-Jan-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Removed
Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added

Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed
Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed
Date	04-Dec-2022
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00000897
Solution Title	Oil consumption related to high blowby
Update Reason	Solution Added

Date	20-Nov-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	12-Nov-2022
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	12-Nov-2022
Fault Code / Symptom	Control Module Identification Input State Error - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	12-Nov-2022
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	12-Nov-2022
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed

Date	12-Nov-2022
Fault Code / Symptom	Auxiliary PWM Driver 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	12-Nov-2022
Fault Code / Symptom	Auxiliary PWM Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	15-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00010993
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	15-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	15-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	08-Oct-2022
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered

Date	08-Oct-2022
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	08-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered
Date	08-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	08-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00000898
Solution Title	Starter magnetic switch is malfunctioning
Update Reason	Solution Reordered
Date	08-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00000898
Solution Title	Starter magnetic switch is malfunctioning
Update Reason	Solution Modified
Date	08-Oct-2022
Fault Code / Symptom	Engine Fuel Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001646
Solution Title	Fuel temperature sensor circuit response at the ECM
Update Reason	Solution Added

Date	08-Oct-2022
Fault Code / Symptom	Engine Fuel Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003696
Solution Title	Fuel rail pressure sensor circuit response at the ECM
Update Reason	Solution Removed
Date	10-Sep-2022
Fault Code / Symptom	
Solution Number	
Solution Title	
Update Reason	QSK60 CM2150 MCRS New manual released for use.

Last Modified: 23-Aug-2026
