



Technical Service Bulletin

Technical Service Bulletin: tsb100796

Released Date: 05-Feb-2020

New Injector Copper Seals

New Injector Copper Seals

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces new injector copper seals of various sizes for the QSK45 and QSK60 engines.

The sizes shown in the table represent the protrusion change. See Procedure 002-004 (Cylinder Head) in the QSK45 and QSK60 Series Service Manual, Bulletin 4021530, for remove and install instructions.

Injector Copper Seal			
New Part Number	Old Part Number	Size mm [in]	Description
5462083	3867687	Standard	Seal, Injector
4307149	3347933	0.254 mm [0.010 in]	Seal, Injector
4307150	3347934	0.508 mm [0.020 in]	Seal, Injector
4307151	3347935	0.762 mm [0.030 in]	Seal, Injector

Note : This is a product improvement and is not subject to campaign.

Document History

Date	Details
2020-2-4	Non-Product Problem Solving (PPS)

Last Modified: 05-Feb-2020