



Technical Service Bulletin

Technical Service Bulletin: tsb100885

Released Date: 27-Mar-2017

New Eliminator™ Bracket

New Eliminator™ Bracket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic announces the release of a new Eliminator™ bracket for use on the QSK 60 engine.

The bracket has been redesigned from a single piece bracket to a three piece bracket to increase robustness.

Figure 1 shows an assembly of the new three piece bracket.

Table 1 shows the old part number, new part numbers, and ESN first.

Use the following procedure for further information on removal and installation of this bracket, in the QSK45 and QSK60 Service Manual, Bulletin 4021530. Refer to Procedure Refer to Procedure 007-067 in Section 7. (</qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html>)

Note : This is a product improvement and is not subject to TRP or Campaign actions.




Figure 1: New Eliminator™ Support Bracket Assembly

Table 1

Engine Model	Old Part Number	New Part Number	Item Number	ESN First
QSK60	4016424	3642189	1	33179329
		3642188	2	
		3642187	3	




Figure 2; Mounting Components

Figure 2 shows where the mounting components are positioned.

Table 2 shows the mounting components that are required to upfit an engine with the new Eliminator™ support bracket assembly.

Table 2, Mounting Components			
Part Number	Description	Item Number	Quantity
3903464	M10 x 1.5 (40 mm length)Capscrew	1	4
3902116	M12 x 1.75 (50 mm length) Capscrew	2	2
3631782	Spacer	3	2
3902662	M10 Nut	4	4
3900635	M10 x 1.5 (60 mm length) Capscrew	5	5
3910495	M12 x 1.75 (30 mm length) Capscrew	6	2

Document History

Date	Details
2017-3-27	Capscrew, Part Number 3900635, quantity updated from 4 to 5.