



Technical Service Bulletin

Technical Service Bulletin: TSB130007

Released Date: 02-May-2018

New Gear Part Numbers for QSK45, QSK60, and QSK78 Engines

New Gear Part Numbers for QSK45, QSK60, and QSK78 Engines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces new gear part numbers for QSK45, QSK60, and QSK78 engines. These new gears have revised dimensional and material specifications.

Gears of the old part number are now obsolete, but the disposition of the old gears varies by part number. Gears from supplier code XHYL may be re-used if they pass re-use inspection. Refer to the table below to determine if old part number gears can be re-used if they are from supplier code AAWCV.

New and Old Part Numbers				
Model	Description	New Part Number	Old Part Number	Old Part Number OK to Re-use
QSK78	Gear, crankshaft, front	3646146	4007558	No
QSK78	Gear, crankshaft, rear	3646147	4007347	Yes
QSK78	Gear, idler, accessory compound	3646070	4007739	No
QSK78	Gear, camshaft idler, compound, left bank	3646069	4007562	No
QSK78	Gear, camshaft idler, right bank	3646765	4007350	No
QSK78	Gear, camshaft, right bank	3646087	4007345	Yes

New and Old Part Numbers				
Model	Description	New Part Number	Old Part Number	Old Part Number OK to Re-use
QSK78	Gear, camshaft, left bank	3646088	4007346	Yes
QSK45/60	Gear, crankshaft	3646083	4015887	Yes
QSK45/60	Gear, idler, accessory compound	3646067	3089121	Yes
QSK45/60	Gear, camshaft idler, compound, left bank	3646066	3089087	No
QSK45/60	Gear, camshaft idler, right bank	3646065	3089091	No
QSK45/60	Gear, camshaft, right bank	3646084	3089081	Yes
QSK45/60	Gear, camshaft, left bank	3646085	3332138	Yes
QSK60 T2 MCRS	Gear, camshaft, left bank, T2 MCRS	3646086	4094564	Yes
QSK60 Gas	Gear, camshaft, left bank, QSK60 Gas	3647167	4066325	Yes
QSK45/60/78	Gear, idler, water pump	3646068	3089105	Yes
QSK45/60/78	Gear, accessory drive	3646082	3089100	Yes*
* Must be labelled Part Number K3089100 or RIC.				

These new gears have been introduced into production at Daventry as follows:

New Gears Introduced At Daventry			
Model	Gear Introduced	Engine Serial Number (ESN) First	Production Date
QSK78	Gear, crankshaft, front (3646146) and gear, camshaft idler, right bank (3646765)	66302559	3rd December 2012

New Gears Introduced At Daventry			
Model	Gear Introduced	Engine Serial Number (ESN) First	Production Date
QSK78	Gear, camshaft idler, compound, left bank (3646069) and Gear, idler, accessory compound (3646070)	66302587	14th December 2012
QSK45/60	Gear, camshaft idler, compound, left bank (3646066)	33196603	17th January 2013
QSK45/60	Gear, camshaft idler, right bank (3646065)	33196739	31st January 2013

All other new part number gears are being phased in over time.

The removal and installation procedures remain unchanged.

Note : Crankshaft and camshaft gears require heating to install. Make sure that the procedures published in the relevant service manuals are followed. Exposing the gears to excessively high temperatures, or heating them for an excessive amount of time, will cause gear damage that can cause gear failure.

Associated Publications

Reference Parts Alerts MDC-005-16 and 046-13 for information on what batches of gears should **not** be used or reused on engines.

Document History

Date	Details
2013-1-2	Module Created
2013-6-24	Add new gear part numbers for QSK45/60 released originally for the QSK78.
2013-8-26	none
2017-7-27	Added reference to Parts Alerts MDC-005-16 and 046-1.
2018-4-30	Updated QSK78 left and right bank camshaft gear rows.

