



Technical Service Bulletin

Technical Service Bulletin: TSB130119

Released Date: 21-Oct-2013

New Rockford® Fan Solenoid Mounting Bracket and Hose

New Rockford® Fan Solenoid Mounting Bracket and Hose

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of a new Rockford® Fan solenoid mounting bracket and hose for QSK45, QSK60, and QSK78 engines. The part number for the existing mounting bracket is being obsoleted and replaced with a modified spacer that has a new part number. The new hose is a different length to comply with the change in position of the solenoid on the new spacer.

Table 1 lists the obsoleted part number for the mounting bracket.

Table 1: Obsoleted Part Number for the Mounting Bracket

Obsoleted Part Number

4086160

Table 2 lists the part numbers for the spacer.

Table 2: Spacer Part Numbers

Old Part Number	New Part Number
-----------------	-----------------

3635316	3649369
---------	---------

Table 3 lists the part numbers for the hose.

Table 3: Hose Part Numbers

Old Part Number	New Part Number
-----------------	-----------------

4015819	3649415
---------	---------

ESN first for the new mounting bracket and hose for QSK45 & QSK60 is 33198642, and for QSK78 is 66302886.

Document History

Date	Details
2013-8-5	Module Created

Last Modified: 21-Oct-2013
