



Technical Service Bulletin

Technical Service Bulletin: TSB230078

Released Date: 14-Apr-2023

Leaking Coolant From Low Temperature Aftercooler (LTA) Core

Leaking Coolant From Low Temperature Aftercooler (LTA) Core

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM850 MCRS
- QSK60 CM2150 K132M
- QSK60 CM2150 MCRS
- QSK60 CM2150 MCRS G

Issue Summary

Symptom:

- Excessive coolant use; external coolant leak

Root Cause:

- Capscrews used for the aftercooler cores are loose or broken; aftercooler core is cracked

Verification

If a coolant leak from the aftercoolers is observed, or excessive coolant use has been confirmed, follow instructions in resolution section.

Resolution

- If a coolant leak from the aftercoolers is verified, replace aftercooler cores and capscrews with new ones.
- A new capscrew part number should be used which allows for a greater torque value. See Table 1 for part numbers.
- For aftercooler core removal and installation instructions, see corresponding Service Manual. Reference Procedure 010-002 in section 10. See Table 3 for Service Manual information.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts					
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number	
Aftercooler core	5543593	No	No	-	
Cap Screw	3902460	No	No	3093932	
Production Status					
Implemented for production. See Table 2.					
Table 2, Production Information					
ESN First		Build Date ¹		Plant	
33231598		Apr 2023		Daventry Engine Plant	
¹ Engine build date can be found on engine dataplate.					
Publications Affected					
Table 3, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QSK60 CM2150 MCRS	4021530	Aftercooler Assembly	Refer to Procedure 010-002 (/qs3/pubsys2/xml/en/procedures/56/56-010-002.html)	10

Document History

Date	Details
2023-4-12	Module Created