



Technical Service Bulletin

Technical Service Bulletin: TSB250124

Released Date: 16-Jun-2025

Hybrid MCRS Fuel Pump Service Kit Upfit

Hybrid MCRS Fuel Pump Service Kit Upfit

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM2150 MCRS

Description of Change

- A new fuel pump and associated hardware has been released to improve reliability of the pumping element plunger.

Reason for Change

- The new fuel pump design has improved fuel flow routing to reduce fuel temperature inside the fuel pump when frequently operating under low load.
- A new high pressure fuel line has been released to allow the new fuel pump to be fitted on two stage turbocharged engines.
- A service kit has been released, containing additional hardware required to upfit an existing engine with the new fuel pump and high-pressure fuel line.

Service Instructions

- Service parts are available. See Table 1 and Table 2. Part numbers vary depending on engine model (single stage or two stage).

Service Parts Availability

- Service parts are available. See Table 1 and Table 2.
- Part numbers vary depending on engine model (single stage or two stage).

Table 1, Service Parts - QSK60 CM2150 MCRS Single Stage

Part Description	Obsolete	Superseded	New Part Number
Fuel pump	No	No	6472212
Service Kit	No	No	6513807

Table 1, Service Parts - QSK60 CM2150 MCRS Single Stage			
Part Description	Obsolete	Superseded	New Part Number
High Pressure Fuel Line (LB)	No	No	5592789
High Pressure Fuel Line (RB)	No	No	5592785
Table 2, Service Parts - QSK60 CM2150 MCRS Two Stage			
Part Description	Obsolete	Superseded	New Part Number
Fuel pump	No	No	6472212
Service Kit	No	No	6513807
High Pressure Fuel Line (LB)	No	No	5592789
High Pressure Fuel Line (RB)	No	No	6556952

Document History

Date	Details
2025-6-10	Module Created