

Manual Change History (3666231) Centinel™ Master Repair Manual

Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-004 (/qs3/pubsys2/xml/en/procedures/99/99-204-004.html)
Procedure Title	Symbols
Update Reason	
Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-005 (/qs3/pubsys2/xml/en/procedures/99/99-204-005.html)
Procedure Title	Illustrations
Update Reason	
Date	03-Apr-2002
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-002 (/qs3/pubsys2/xml/en/procedures/99/99-t00-002.html)
Procedure Title	Troubleshooting Symptoms Charts
Update Reason	
Date	10-Jul-2002
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-220 (/qs3/pubsys2/xml/en/procedures/99/99-019-220.html)
Procedure Title	Augat Connector Series
Update Reason	

Date	03-Apr-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-197 (/qs3/pubsys2/xml/en/procedures/99/99-019-197.html)
Procedure Title	Ring Terminal
Update Reason	
Date	03-Apr-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-198 (/qs3/pubsys2/xml/en/procedures/99/99-019-198.html)
Procedure Title	Fuse, Harness In-Line
Update Reason	
Date	03-Apr-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-199 (/qs3/pubsys2/xml/en/procedures/99/99-019-199.html)
Procedure Title	Connector, Butt Splice
Update Reason	
Date	03-Apr-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-202 (/qs3/pubsys2/xml/en/procedures/99/99-019-202.html)
Procedure Title	Metripack Connector Series
Update Reason	

Date	03-Apr-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-203 (/qs3/pubsys2/xml/en/procedures/99/99-019-203.html)
Procedure Title	AMP Connector Series
Update Reason	
Date	03-Apr-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-204 (/qs3/pubsys2/xml/en/procedures/99/99-019-204.html)
Procedure Title	Deutsch DRC Connector Series
Update Reason	
Date	03-Apr-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-206 (/qs3/pubsys2/xml/en/procedures/99/99-019-206.html)
Procedure Title	Deutsch DTM and DTP Connector Series
Update Reason	
Date	03-Apr-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-209 (/qs3/pubsys2/xml/en/procedures/99/99-019-209.html)
Procedure Title	ITT Cannon Connector Series
Update Reason	

Date	09-Oct-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-201 (/qs3/pubsys2/xml/en/procedures/99/99-019-201.html)
Procedure Title	Weather Pak Connector Series
Update Reason	
Date	09-Oct-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-205 (/qs3/pubsys2/xml/en/procedures/99/99-019-205.html)
Procedure Title	Deutsch DT Connector Series
Update Reason	
Date	09-Oct-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-207 (/qs3/pubsys2/xml/en/procedures/99/99-019-207.html)
Procedure Title	Deutsch HD10 Connector Series
Update Reason	
Date	09-Oct-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-210 (/qs3/pubsys2/xml/en/procedures/99/99-019-210.html)
Procedure Title	AMP VP44 Connector Series
Update Reason	

Date	09-Oct-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-211 (/qs3/pubsys2/xml/en/procedures/99/99-019-211.html)
Procedure Title	Packard Relay Connector
Update Reason	
Date	09-Oct-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-212 (/qs3/pubsys2/xml/en/procedures/99/99-019-212.html)
Procedure Title	Ford™ Connector Series
Update Reason	
Date	09-Oct-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-213 (/qs3/pubsys2/xml/en/procedures/99/99-019-213.html)
Procedure Title	D-Sub Miniature Connector Series
Update Reason	
Date	09-Oct-2003
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-218 (/qs3/pubsys2/xml/en/procedures/99/99-019-218.html)
Procedure Title	Framatome Connector Series
Update Reason	

Date	25-Feb-2004
Section	Section E - Component Identification
Procedure Number	96-208-002 (/qs3/pubsys2/xml/en/procedures/96/96-208-002.html)
Procedure Title	Component Diagrams
Update Reason	
Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc118 (/qs3/pubsys2/xml/en/procedures/96/96-fc118.html)
Procedure Title	Fuel Rail Pressure Sensor Circuit - Out of Range High
Update Reason	
Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc119 (/qs3/pubsys2/xml/en/procedures/96/96-fc119.html)
Procedure Title	Fuel Rail Pressure Sensor Circuit - Out of Range Low
Update Reason	
Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc198 (/qs3/pubsys2/xml/en/procedures/96/96-fc198.html)
Procedure Title	Diagnostic Lamp Circuit - Open Circuit
Update Reason	
Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc219 (/qs3/pubsys2/xml/en/procedures/96/96-fc219.html)
Procedure Title	Make-Up Tank Oil Level Low
Update Reason	

Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc223 (/qs3/pubsys2/xml/en/procedures/96/96-fc223.html)
Procedure Title	Burn Valve Solenoid Circuit - Open Circuit
Update Reason	
Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc224 (/qs3/pubsys2/xml/en/procedures/96/96-fc224.html)
Procedure Title	Burn Valve Solenoid Circuit - Short Circuit
Update Reason	
Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc327 (/qs3/pubsys2/xml/en/procedures/96/96-fc327.html)
Procedure Title	Fuel Rate - Out of Range High
Update Reason	
Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc342 (/qs3/pubsys2/xml/en/procedures/96/96-fc342.html)
Procedure Title	Centinel™ Control Module Calibration Plug Malfunctioning
Update Reason	
Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc414 (/qs3/pubsys2/xml/en/procedures/96/96-fc414.html)
Procedure Title	J1587 Data Link Time-Out
Update Reason	

Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc441 (/qs3/pubsys2/xml/en/procedures/96/96-fc441.html)
Procedure Title	Battery Voltage - Out of Range Low
Update Reason	
Date	25-Feb-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc442 (/qs3/pubsys2/xml/en/procedures/96/96-fc442.html)
Procedure Title	Battery Voltage - Out of Range High
Update Reason	
Date	25-Feb-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	96-022-001 (/qs3/pubsys2/xml/en/procedures/96/96-022-001.html)
Procedure Title	Service Tools
Update Reason	
Date	25-Feb-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	96-022-015 (/qs3/pubsys2/xml/en/procedures/96/96-022-015.html)
Procedure Title	Wiring Harness Repair Kit
Update Reason	

Date	25-Feb-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	96-019-139 (/qs3/pubsys2/xml/en/procedures/96/96-019-139.html)
Procedure Title	Centinel™ Control Solenoid Circuit
Update Reason	
Date	03-Mar-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc111 (/qs3/pubsys2/xml/en/procedures/96/96-fc111.html)
Procedure Title	Centinel™ Control Module Error
Update Reason	
Date	03-Mar-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc199 (/qs3/pubsys2/xml/en/procedures/96/96-fc199.html)
Procedure Title	Diagnostic Lamp Circuit - Short Circuit
Update Reason	
Date	03-Mar-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc225 (/qs3/pubsys2/xml/en/procedures/96/96-fc225.html)
Procedure Title	Make-Up Valve Solenoid Circuit - Open Circuit
Update Reason	
Date	03-Mar-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc226 (/qs3/pubsys2/xml/en/procedures/96/96-fc226.html)
Procedure Title	Make-Up Valve Solenoid Circuit - Short Circuit
Update Reason	

Date	03-Mar-2004
Section	Section TF - Troubleshooting Fault Codes
Procedure Number	96-fc649 (/qs3/pubsys2/xml/en/procedures/96/96-fc649.html)
Procedure Title	Oil Change Required
Update Reason	
Date	03-Mar-2004
Section	Section L - Service Literature
Procedure Number	96-205-001 (/qs3/pubsys2/xml/en/procedures/96/96-205-001.html)
Procedure Title	Additional Service Literature
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-010 (/qs3/pubsys2/xml/en/procedures/99/99-018-010.html)
Procedure Title	Fraction, Decimal, Millimeter Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-011 (/qs3/pubsys2/xml/en/procedures/99/99-018-011.html)
Procedure Title	Newton-Meter to Foot-Pound Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-012 (/qs3/pubsys2/xml/en/procedures/99/99-018-012.html)
Procedure Title	Pipe Plug Torque Values
Update Reason	

Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-013 (/qs3/pubsys2/xml/en/procedures/99/99-018-013.html)
Procedure Title	Tap-Drill Chart - U.S. Customary and Metric
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-014 (/qs3/pubsys2/xml/en/procedures/99/99-018-014.html)
Procedure Title	Weights and Measures - Conversion Factors
Update Reason	
Date	20-Apr-2004
Section	Front
Procedure Number	3666231-titlepage (/qs3/pubsys2/xml/en/manual/3666231/3666231-titlepage.html)
Procedure Title	Titlepage
Update Reason	
Date	20-Apr-2004
Section	Front
Procedure Number	3666231-toc (/qs3/pubsys2/xml/en/manual/3666231/3666231-toc.html)
Procedure Title	Table of Contents
Update Reason	
Date	20-Apr-2004
Section	Section F - Familiarization
Procedure Number	96-007-999 (/qs3/pubsys2/xml/en/procedures/96/96-007-999.html)
Procedure Title	Lubricating Oil System - Overview
Update Reason	

Date	20-Apr-2004
Section	Section G - Installation Guidelines
Procedure Number	96-007-078 (/qs3/pubsys2/xml/en/procedures/96/96-007-078.html)
Procedure Title	Centinel™ Oil Control Valve
Update Reason	
Date	20-Apr-2004
Section	Section 2 - Maintenance Guidelines
Procedure Number	96-102-002 (/qs3/pubsys2/xml/en/procedures/96/96-102-002.html)
Procedure Title	Maintenance Schedule
Update Reason	
Date	20-Apr-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	96-007-076 (/qs3/pubsys2/xml/en/procedures/96/96-007-076.html)
Procedure Title	Burn Solenoid
Update Reason	
Date	20-Apr-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	96-007-078-tr (/qs3/pubsys2/xml/en/procedures/96/96-007-078-tr.html)
Procedure Title	Centinel™ Oil Control Valve
Update Reason	
Date	20-Apr-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	96-007-083 (/qs3/pubsys2/xml/en/procedures/96/96-007-083.html)
Procedure Title	Lubricating Oil and Filter Analysis
Update Reason	

Date	20-Apr-2004
Section	Section V - Specifications
Procedure Number	96-018-003 (/qs3/pubsys2/xml/en/procedures/96/96-018-003.html)
Procedure Title	Lubricating Oil Recommendations and Specifications
Update Reason	
Date	20-Apr-2004
Section	Back
Procedure Number	3666231-backcover (/qs3/pubsys2/xml/en/manual/3666231/3666231-backcover.html)
Procedure Title	Backcover
Update Reason	
Date	22-Apr-2004
Section	Section E - Component Identification
Procedure Number	96-208-001 (/qs3/pubsys2/xml/en/procedures/96/96-208-001.html)
Procedure Title	Component Identification
Update Reason	
Date	22-Apr-2004
Section	Section F - Familiarization
Procedure Number	96-209-001 (/qs3/pubsys2/xml/en/procedures/96/96-209-001.html)
Procedure Title	System Description
Update Reason	
Date	22-Apr-2004
Section	Section G - Installation Guidelines
Procedure Number	96-019-130 (/qs3/pubsys2/xml/en/procedures/96/96-019-130.html)
Procedure Title	Centinel™ Control Module
Update Reason	

Date	22-Apr-2004
Section	Section G - Installation Guidelines
Procedure Number	96-019-056 (/qs3/pubsys2/xml/en/procedures/96/96-019-056.html)
Procedure Title	Lubricating Oil Level Sensor
Update Reason	
Date	22-Apr-2004
Section	Section G - Installation Guidelines
Procedure Number	96-007-091 (/qs3/pubsys2/xml/en/procedures/96/96-007-091.html)
Procedure Title	Centinel™ Decals
Update Reason	
Date	22-Apr-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	96-007-077 (/qs3/pubsys2/xml/en/procedures/96/96-007-077.html)
Procedure Title	Make-Up Solenoid
Update Reason	
Date	22-Apr-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	96-019-056-tr (/qs3/pubsys2/xml/en/procedures/96/96-019-056-tr.html)
Procedure Title	Lubricating Oil Level Sensor
Update Reason	
Date	22-Apr-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	96-019-115 (/qs3/pubsys2/xml/en/procedures/96/96-019-115.html)
Procedure Title	Rail Fuel Pressure Sensor
Update Reason	

Date	22-Apr-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	96-019-130-tr (/qs3/pubsys2/xml/en/procedures/96/96-019-130-tr.html)
Procedure Title	Centinel™ Control Module
Update Reason	
Date	22-Apr-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	96-019-138 (/qs3/pubsys2/xml/en/procedures/96/96-019-138.html)
Procedure Title	Centinel™ Control Solenoids
Update Reason	
Date	28-Apr-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666231-t081-003-tr (/qs3/pubsys2/xml/en/manual/3666231/3666231-t081-003-tr.html)
Procedure Title	Excessive Use of Engine Lubricating Oil From the Pan With Burn-Only System (oil level in pan below normal)
Update Reason	
Date	28-Apr-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666231-t095-156-tr (/qs3/pubsys2/xml/en/manual/3666231/3666231-t095-156-tr.html)
Procedure Title	Inadequate Use of Engine Lubricating Oil From Pan With Burn-Only System
Update Reason	

Date	28-Apr-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666231-t102-25-tr (/qs3/pubsys2/xml/en/manual/3666231/3666231-t102-25-tr.html)
Procedure Title	Lubricating Oil Consumption From Oil Make-Up Tank Excessive
Update Reason	
Date	28-Apr-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666231-t103-25-tr (/qs3/pubsys2/xml/en/manual/3666231/3666231-t103-25-tr.html)
Procedure Title	Engine Lubricating Oil Level Above Specifications While Using Correct Amount of Make-Up Oil
Update Reason	
Date	28-Apr-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666231-t103-5-tr (/qs3/pubsys2/xml/en/manual/3666231/3666231-t103-5-tr.html)
Procedure Title	Lubricating Oil Level Below Specifications While Using Correct Amount of Make-Up Oil
Update Reason	
Date	28-Apr-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666231-t108-5-tr (/qs3/pubsys2/xml/en/manual/3666231/3666231-t108-5-tr.html)
Procedure Title	No Electrical Power to Centinel Control Module (not applicable for integrated system)
Update Reason	

Date	28-Apr-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	96-019-026 (/qs3/pubsys2/xml/en/procedures/96/96-019-026.html)
Procedure Title	Data Link Circuit, Public
Update Reason	
Date	29-Apr-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666231-t102-5-tr (/qs3/pubsys2/xml/en/manual/3666231/3666231-t102-5-tr.html)
Procedure Title	Engine Lubricating Oil Consumption From Oil Make-Up Tank Inadequate
Update Reason	
Date	29-Apr-2004
Section	Section G - Installation Guidelines
Procedure Number	96-007-090 (/qs3/pubsys2/xml/en/procedures/96/96-007-090.html)
Procedure Title	Centinel™ Control Module Mounting Bracket
Update Reason	
Date	29-Apr-2004
Section	Section G - Installation Guidelines
Procedure Number	96-007-088 (/qs3/pubsys2/xml/en/procedures/96/96-007-088.html)
Procedure Title	Centinel™ Oil Lines
Update Reason	
Date	29-Apr-2004
Section	Section G - Installation Guidelines
Procedure Number	96-007-089-shopas (/qs3/pubsys2/xml/en/procedures/96/96-007-089-shopas.html)
Procedure Title	Centinel™ Oil Make-Up Tank
Update Reason	

Date	29-Apr-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	96-007-088-tr (/qs3/pubsys2/xml/en/procedures/96/96-007-088-tr.html)
Procedure Title	Centinel™ Oil Lines
Update Reason	
Date	29-Apr-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	96-007-089 (/qs3/pubsys2/xml/en/procedures/96/96-007-089.html)
Procedure Title	Centinel™ Oil Make-Up Tank
Update Reason	
Date	29-Apr-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	96-007-090-tr (/qs3/pubsys2/xml/en/procedures/96/96-007-090-tr.html)
Procedure Title	Centinel™ Control Module Mounting Bracket
Update Reason	
Date	10-May-2004
Section	Section G - Installation Guidelines
Procedure Number	96-019-131 (/qs3/pubsys2/xml/en/procedures/96/96-019-131.html)
Procedure Title	Centinel™ Wiring Harness
Update Reason	
Date	10-May-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	96-019-131-tr (/qs3/pubsys2/xml/en/procedures/96/96-019-131-tr.html)
Procedure Title	Centinel™ Wiring Harness
Update Reason	

Date	09-Jun-2004
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-208 (/qs3/pubsys2/xml/en/procedures/99/99-019-208.html)
Procedure Title	Deutsch HDP20 and HD30 Connector Series
Update Reason	
Date	02-Nov-2005
Section	Section V - Specifications
Procedure Number	96-018-017 (/qs3/pubsys2/xml/en/procedures/96/96-018-017.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	22-May-2006
Section	Front
Procedure Number	tr-frwd (/qs3/pubsys2/xml/en/manual/preface/tr-frwd.html)
Procedure Title	Foreword
Update Reason	
Date	27-Jun-2006
Section	Section L - Service Literature
Procedure Number	99-205-002 (/qs3/pubsys2/xml/en/procedures/99/99-205-002.html)
Procedure Title	Service Literature Ordering Location
Update Reason	
Date	24-Jul-2007
Section	Section i - Introduction
Procedure Number	99-204-008 (/qs3/pubsys2/xml/en/procedures/99/99-204-008.html)
Procedure Title	General Cleaning Instructions
Update Reason	

Date	30-May-2008
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-008 (/qs3/pubsys2/xml/en/procedures/99/99-019-008.html)
Procedure Title	Battery Ground Circuit
Update Reason	
Date	19-Mar-2009
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-214 (/qs3/pubsys2/xml/en/procedures/99/99-019-214.html)
Procedure Title	Bosch® Actuator and Sensor Connector Series
Update Reason	
Date	19-Mar-2009
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-215 (/qs3/pubsys2/xml/en/procedures/99/99-019-215.html)
Procedure Title	Bosch® ECM Injector Driver Connector Series
Update Reason	
Date	23-Apr-2009
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-216 (/qs3/pubsys2/xml/en/procedures/99/99-019-216.html)
Procedure Title	Bosch® ECM Actuator and Sensor Connector Series
Update Reason	

Date	23-Apr-2009
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-217 (/qs3/pubsys2/xml/en/procedures/99/99-019-217.html)
Procedure Title	Bosch® ECM OEM Connector Series
Update Reason	
Date	25-Jun-2009
Section	Section i - Introduction
Procedure Number	99-204-006-mrm (/qs3/pubsys2/xml/en/procedures/99/99-204-006-mrm.html)
Procedure Title	General Safety Instructions
Update Reason	
Date	25-Jun-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-001-tr (/qs3/pubsys2/xml/en/procedures/99/99-t00-001-tr.html)
Procedure Title	Troubleshooting Procedures and Techniques
Update Reason	
Date	22-Jul-2009
Section	Section L - Service Literature
Procedure Number	99-205-004 (/qs3/pubsys2/xml/en/procedures/99/99-205-004.html)
Procedure Title	Cummins Customized Parts Catalog
Update Reason	
Date	10-Sep-2009
Section	Section i - Introduction
Procedure Number	99-204-002-mrm (/qs3/pubsys2/xml/en/procedures/99/99-204-002-mrm.html)
Procedure Title	About the Manual
Update Reason	

Date	08-Oct-2009
Section	Section i - Introduction
Procedure Number	99-204-007-mrm (/qs3/pubsys2/xml/en/procedures/99/99-204-007-mrm.html)
Procedure Title	General Repair Instructions
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-005 (/qs3/pubsys2/xml/en/procedures/99/99-018-005.html)
Procedure Title	Drive Belt Tension
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-009 (/qs3/pubsys2/xml/en/procedures/99/99-018-009.html)
Procedure Title	Capscrew Markings and Torque Values
Update Reason	
Date	24-Mar-2010
Section	Section i - Introduction
Procedure Number	99-204-009 (/qs3/pubsys2/xml/en/procedures/99/99-204-009.html)
Procedure Title	Acronyms and Abbreviations
Update Reason	
Date	25-May-2010
Section	Section i - Introduction
Procedure Number	99-204-003-mrm (/qs3/pubsys2/xml/en/procedures/99/99-204-003-mrm.html)
Procedure Title	How to Use the Manual
Update Reason	

Date	16-Jun-2010
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	105-019-032 (/qs3/pubsys2/xml/en/procedures/105/105-019-032.html)
Procedure Title	ECM Calibration Code
Update Reason	
Date	17-Aug-2010
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	99-019-474 (/qs3/pubsys2/xml/en/procedures/99/99-019-474.html)
Procedure Title	Bosch Aftertreatment DEF Controller Connector
Update Reason	Added procedure to outline.
Date	17-Jun-2011
Section	Section 2 - Maintenance Guidelines
Procedure Number	96-102-002 (/qs3/pubsys2/xml/en/procedures/96/96-102-002.html)
Procedure Title	Maintenance Schedule
Update Reason	Update General Information section with procedure link to the QSK78 O&M manual, Bulletin 3666714.
Date	10-Feb-2012
Section	Section 19 - Electronic Engine Controls - Group 19
Procedure Number	105-019-032 (/qs3/pubsys2/xml/en/procedures/105/105-019-032.html)
Procedure Title	ECM Calibration Code
Update Reason	Updated to include information concerning troubleshooting of ECM calibration issues once new calibration is installed.

Date	10-Apr-2014
Section	Section F - Familiarization
Procedure Number	96-209-001 (/qs3/pubsys2/xml/en/procedures/96/96-209-001.html)
Procedure Title	System Description
Update Reason	Updated the contents to current status by adding missing engine families where Centine™I system can be installed and use restrictions information related to introduction of products using SCR aftertreatments systems.

Date	21-Oct-2019
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	105-019-032 (/qs3/pubsys2/xml/en/procedures/105/105-019-032.html)
Procedure Title	Engine Control Module Calibration Code
Update Reason	Added a statement to have the technician "verify vehicle odometer is equal to the value recorded before ECM removal."

Last Modified: 07-Nov-2019
