



Technical Service Bulletin

Technical Service Bulletin: tsb100051	Released Date: 17-Jun-2010
INSITE™ 7.4 Features and Parameters Display Issue	

INSITE™ 7.4 Features and Parameters Display Issue

Core Issue

This Technical Service Bulletin describes an issue with INSITE™ electronic service tool version 7.4 (7.4.0.244) displaying the Features and Parameters column incorrectly (too narrow). This causes the rows to widen and makes it difficult to read the feature names.

Confirmation

All Engines supported by INSITE™ electronic service tool.

Open Features and Parameters while connected to an ECM and the first column is narrow and the rows are wide.

None


INSITE™ electronic service tool version 7.4 (7.4.0.244) is automatically adjusting the first column width incorrectly on some screen resolutions.

None

Resolution


Manually adjust the width of the first column:

- Move the cursor over the column line until it changes to a double arrow.
- While holding the left mouse button down, move the column line to the right until the column width has increased and then release the mouse button.



22000028

After resizing the column, the row width will automatically adjust.



22000029

Change the display resolution to any of the following settings:

- 800 by 600
- 1024 by 768
- 1280 by Any
- 1152 by 864

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 17-Jun-2010
