



Technical Service Bulletin

Technical Service Bulletin: tsb100128

Released Date: 16-Nov-2001

Prelub™ System Changes

Prelub™ System Changes

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin describes design modifications made to the QST30 Prelub™ system.

The Prelub system on QST30 industrial engines has been redesigned to improve functionality and reliability. The first engine with the redesigned components was engine serial number 37197070, which was built on January 22, 2001. Komatsu-branded engines built between January 22 and March 23, 2001, use the new Prelub components. All industrial engines built after March 23, 2001, also have the new components installed. The following summarizes the changes.

Pressure Switch

The Prelub pressure switch mounts next to the main oil pressure sensor on the engine's left bank. This normally closed switch senses left-bank piston-cooling rifle pressure. When oil pressure exceeds the set point, the switch opens.

The old pressure switch, Part Number 3094400, was set at 27.5 kPa [4 psi]; the new pressure switch, Part Number 4065465, is set at 17 kPa [2.5 psi]. The set point has been lowered to reduce the prelubrication time while starting a warm engine. In addition, the new pressure switch uses a Packard electrical connector that is different from the old connector. The Packard connector provides improved resistance to environmental conditions.

Timer Solenoid

The new relay switch, or timer solenoid, is Part Number 3633715. It functions the same as the old timer; however, several changes have been made to improve durability. In addition, the mounting bolt pattern is larger on the new timer solenoid mounting bracket. Slight modification will be needed to mount the new timer solenoid if replacing the old one.

Wiring Harness

The new Prelub wiring harness includes a 300-amp in-line fusing element between the timer solenoid and the Prelub starter battery terminal. The harness also uses a Packard connector to connect with the new pressure switch. The new Prelub wiring harness part numbers are:

- 3094851, Komatsu WA800 and WA900 loaders
- 3094120, Komatsu 330M and 785-5 haul trucks
- 3094118, all other industrial engines.

Note : This is a product improvement and is not subject to campaign.

Last Modified: 16-Nov-2001
