



Technical Service Bulletin

Technical Service Bulletin: tsb100383

Released Date: 23-Aug-2005

New High Horsepower Machined-from-Solid Turbocharger Compressor Wheel

New High Horsepower Machined-from-Solid Turbocharger Compressor Wheel

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces a new machined-from-solid turbocharger compressor wheel for QST30 engines operating in specific applications. The new turbocharger was released to resolve low-cycle fatigue issues.

The previous compressor wheel is cast with the outer blade contour machined to achieve the desired profile. The sides of the cast wheel blades are left in the 'as cast' condition.

The new compressor wheel is machined from a solid billet of aluminum to reduce the number of inclusions in the wheel. All surfaces of the machined-from-solid wheel are machined.

This product improvement is **not** covered by warranty.

Only certain, high-duty cycle applications require the use of turbochargers with machined-from-solid turbocharger compressor wheels.

Consult QuickServe® Online to determine if a given engine and application combination is eligible to receive this product improvement.

Note : This is a product improvement and is not subject to campaign.

The compatibility chart below shows the machined-from-solid turbocharger compressor wheel that can potentially be used with the CPL listed.

Engine	New CPL	Old CPL	Turbocharger with Cast Compressor Wheels	Turbocharger with MFS Compressor Wheels	MFS Service Kit	MFS ReCon®	Direct Supersession?
QST30	0191	2640	3592968	4039206	4090019	N/A	Yes

