



Technical Service Bulletin

Technical Service Bulletin: tsb100542

Released Date: 15-Jan-2007

New Fuel Shutoff Valve

New Fuel Shutoff Valve

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a new fuel shutoff valve and all the associated parts that are now available for the QST30 engine (all applications).

The new fuel shutoff valve features the following product improvements:

- modified wear plate designed to conform with other high horsepower engine families
- modified fuel manifold counter bore depth to adjust for wear plate
- new actuator disc for improved flow characteristics.

The engine serial number (ESN) first for the new fuel shutoff valve is 37226082 and occurred on November 1, 2006.

The new fuel manifold assembly obsoletes and supersedes the old fuel manifold assembly.

New and Old Fuel Shutoff Valve Part Numbers		
Description	Old Part Number	New Part Number
Assembly, fuel manifold	3093521	4295494
- Spring, valve	- 129768	- 129768
- Housing, actuator	- Not applicable	- 4088863
- Shield, shutoff valve	- 129839	- 129839
- Screw, captive washer	- Not applicable	- 3065944
- Disc, valve	- 196057	- 196057
- Solenoid	- 3021420	- 3021420
- Disc, actuator	- 3056009	- 4088274
- Seal, rectangular ring	- 3094667	- 3094667
- Seal, rectangular ring	- Not applicable	- 129888

Note : This is a product improvement and is not subject to campaign.

