



Technical Service Bulletin

Technical Service Bulletin: tsb100564

Released Date: 26-Feb-2007

New One Piece Wiring Harness with Electric Lift Pump Logic

New One Piece Wiring Harness with Electric Lift Pump Logic

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a new one piece wiring harness and fuel extension harness that are available for all QST30 engine applications that use an electric fuel lift pump. The new one piece harness utilizes an additional oil temperature sensor breakout for an optional sensor on the left bank front oil port. The new harness is grounded through the ECM connection so it does **not** require a ground connection to the engine block.

The new part was introduced with Engine Serial Number (ESN) first 37226833 on January 30, 2007.

New sensor part numbers, shown below, are required with the implementation of the new one piece wiring harness and fuel system extension harness.

Old Part Number	Quantity	New Part Number	Description	Location
3093261, 3093363, 3658785	1	4067866	Harness, ETR CNT MDL WRG (One Piece Harness)	
4068024	1	4295539	Harness, Wiring (Fuel System Extension Harness)	
3408589	2	3408556	Sensor, Pressure (Right Bank and Left Bank Intake Manifold Pressure)	Left Bank and Right Bank Intake Manifolds

Old Part Number	Quantity	New Part Number	Description	Location
3408587	1	3408560	Sensor, Pressure (Oil Pressure)	Left Bank, Middle Port on Oil Rifle
N/A	1	3865346	Sensor, Temperature (Oil Temperature)	Left Bank, Front Port on Oil Rifle
N/A	8	4295622	Grommet	ECM Connector Cover

Last Modified: 26-Feb-2007
