



Technical Service Bulletin

Technical Service Bulletin: tsb100600	Released Date: 26-Jun-2007
New Fan Tensioner Options	

New Fan Tensioner Options

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces the release of new industrial fan tensioner options for the QST30 engine.

The QST30 Power Generation fan tensioner is released on the Industrial application.

The new tensioner is included in the following options:

- FA5085
- FA5086

The previous industrial fan tensioner options included:

- FA5073
- FA5076

Last Modified: 26-Jun-2007
