



Technical Service Bulletin

Technical Service Bulletin: tsb100898

Released Date: 11-Dec-2009

New Fuel Pump Pressure Regulator Valve

New Fuel Pump Pressure Regulator Valve

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a new pressure regulator valve for the existing Bosch™ RP39 Injection fuel pump for the QST30 engine (Industrial applications). This is applicable to both mechanical fuel systems and electronic fuel systems.

The pressure regulator valve, Part Number 4975645, replaces the overflow valve, Part Number 3092734. This replacement was made to improve part reliability and proper regulation of the internal fuel pump pressure.

The noun name of this part has changed from overflow valve to pressure regulator valve, as it more accurately describes the part's function.

The engine serial number (ESN) first for the new pressure regulator is 37242280 and occurred on 21-Dec-2009.

The new pressure regulator valve, Part Number 4975645, obsoletes and supersedes the overflow valve, Part Number 3092637, for RP39 model fuel pumps **ONLY**. This valve can **only** be purchased as a kit, Part Number 2881831. The details are shown in the table below.

Valve Kit				
Description	Quantity	Old Part Number	New Part Number	
Kit, Pressure Regulator Valve (formerly Kit, Overflow Valve)		3800696	2881831	
Valve, pressure regulator (formerly valve, overflow)	1	3092734	4975645	

Valve Kit			
Description	Quantity	Old Part Number	New Part Number
Washer, Sealing	2	3963988	4975529

Note : Valve Kit, Part Number 3800696, is still available for power generation applications.

Valve Kit, Part Number 3800697, is now obsolete.

Old Mechanical RP39 Fuel Pumps		
Description	Kit Part Number	Part Number
Left Bank	4025260	3094347
Right Bank	4025261	3094348

New Mechanical Left Bank Kit		
Description	Quantity	Part Number
Kit, Fuel Pump, Left Bank		2881832
Pump, Fuel Injection	1	3094347
Valve, Pressure Regulator	1	4975645
Washer, Sealing	2	4975529

New Mechanical Right Bank Kit		
Description	Quantity	Part Number
Kit, Fuel Pump, Right Bank		2881833
Pump, Fuel Injection	1	3094348
Valve, Pressure Regulator	1	4975645
Washer, Sealing	2	4975529

Note : Previous service kits, Part Numbers 4025260 and 4025261, for the mechanical pumps that included a spline gear, and mounting hardware, are now obsolete.

If the existing pump **must** be replaced or taken to an authorized Bosch™ repair location for service, the spline adapter **must** be removed. Replacement fuel injection pumps do **not** include spline adapters. Use the following procedure in the QST30 Service Manual, Bulletin 4021539. Refer to Procedure 005-012 in Section 5. (</qs3/pubsys2/xml/en/procedures/57/57-005-012-tr.html>)

Old Electronic RP39 Fuel Pumps			
Description	Kit Part Number	Part Number	
Left Bank	N/A	3093636	
Right Bank	N/A	3093635	
New Electronic Left Bank Kit			
Description	Quantity	Part Number	
Kit, Fuel Pump, Left Bank		2881834	
Pump, Fuel Injection	1	3093636	
Valve, Pressure Regulator	1	4975645	
Washer, Sealing	2	4975529	
New Electronic Right Bank Kit			
Description	Quantity	Part Number	
Kit, Fuel Pump, Right Bank		2881835	
Pump, Fuel Injection	1	3093635	
Valve, Pressure Regulator	1	4975645	
Washer, Sealing	2	4975529	

If the existing pump **must** be replaced or taken to an authorized Bosch™ repair location for service, the spline adapter **must** be removed. Replacement fuel injection pumps do **not** include spline adapters. Use the following procedure in the QST30 Service Manual, Bulletin 4021539. Refer to Procedure 005-012 in Section 5. (/qs3/pubsys2/xml/en/procedures/57/57-005-012-tr.html)