



Technical Service Bulletin

Technical Service Bulletin: TSB101052

Released Date: 27-Sep-2010

Cylinder Head Reuse Guidelines Update

Cylinder Head Reuse Guidelines Update

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces changes and additions to the Clean and Inspect for Reuse section of Procedure 002-004 (Cylinder Head) in the QST30 Service Manual, Bulletin 4021539.

The changes include new reuse guidelines for:

- Valve guide inside diameter
- Valve stem diameter
- Valve head height.

Refer to Procedure 002-004 in Section 2. (</qs3/pubsys2/xml/en/procedures/57/57-002-004-tr.html>)

Document History

Date	Details
2010-9-14	Module Created

Last Modified: 27-Sep-2010