



Technical Service Bulletin

Technical Service Bulletin: tsb101364	Released Date: 20-Jan-2004
Centinel™ Feature Update	

Centinel™ Feature Update

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Centinel™ Feature.

Related Procedures

104-214-013-tr (/qs3/pubsys2/xml/en/procedures/104/104-214-013-tr.html)	Centinel™ (/qs3/pubsys2/xml/en/procedures/104/104-214-013-tr.html)
--	---

Last Modified: 20-Jan-2004
