



Technical Service Bulletin

Technical Service Bulletin: tsb101365

Released Date: 27-Jan-2004

Centinel™ System Description

Centinel™ System Description

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates the System Description (209-001) of the Centinel™ Master Repair Manual.

Related Procedures

96-209-001
(/qs3/pubsys2/xml/en/procedures/96/96-209-001.html)

System Description
(/qs3/pubsys2/xml/en/procedures/96/96-209-001.html)

Last Modified: 27-Jan-2004