



Technical Service Bulletin

Technical Service Bulletin: tsb101519

Released Date: 29-Oct-2004

New General Cleaning Instruction

New General Cleaning Instruction

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic is a revision to Procedure 204-008 (</qs3/pubsys2/xml/en/procedures/99/99-204-008.html>) for General Cleaning Instructions.

Considerable concern has been generated at both the factory and the field about engine failures that occur a short time after an in-frame repair. Analysis of returned parts indicates many of the failures are the result of dirt entering the engine during the repair. In particular, intensive investigation of failures of ISX engines rod and main bearings very soon after field repairs of the oil coolers, front gear cover, or cylinder head has shown that 30 percent of the failures are due to contamination of some main oil drillings. Investigation into the type and source of the contamination indicates it is appropriate to remind, review, and revise parts cleaning instructions for all engines.

The statement 'A person can spend too much time cleaning parts but a person can **not** get them too clean' is even more relevant as customer expectations and regulatory requirements increase. These demands coupled with increased diesel engine product complexity place more pressure on the field technician in terms of time required to perform a quality repair. In a effort to reduce customer downtime, many different labor saving devices, techniques, and shortcuts are being used to meet customer expectations. However, some of the shortcuts and labor saving efforts are the very things that can cause contamination of internal engine components that lead to additional failures.

Attached is the revised General Cleaning Instructions that will be placed in all service publications where those instructions are included. Field shops are strongly encouraged to review these instructions with all technicians and to include general cleaning instructions in technician training programs and new technician orientation programs.

Note : This is a product improvement not subject to campaign.

Related Procedures

99-204-008 (/qs3/pubsys2/xml/en/procedures/99/99-204-008.html)	General Cleaning Instructions (/qs3/pubsys2/xml/en/procedures/99/99-204-008.html)
---	--

Last Modified: 29-Oct-2004
