



Technical Service Bulletin: tsb101586

Released Date: 28-Jan-2005

New Oil Suction Tube Bracket

New Oil Suction Tube Bracket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts topic introduces a new oil suction tube bracket for the QST30 Industrial engines.


The existing bracket is a singular column of angled iron shown in Figure 1 and will continue to be used on Power Generation engines. The new Industrial bracket is triangular in shape and is shown in Figure 2.

©Cummins Inc



07a00141

Figure 1, Existing Singular Column Bracket



07a00142

Figure 2, New Triangular Shaped Bracket

The repair procedures will **not** change.

Existing Part Number	New Part Number	Quantity	Description
3094397	4068734	1	Bracket, oil tube

Note : This is a product improvement and is **not** subject to campaign.

Related Procedures

57-007-031-tr (/qs3/pubsys2/xml/en/procedures/57/57-007-031-tr.html)	Lubricating Oil Pump (/qs3/pubsys2/xml/en/procedures/57/57-007-031-tr.html)
57-007-035 (/qs3/pubsys2/xml/en/procedures/57/57-007-035.html)	Lubricating Oil Suction Tube (Block-Mounted) (/qs3/pubsys2/xml/en/procedures/57/57-007-035.html)

