



Technical Service Bulletin

Technical Service Bulletin: tsb103985

Released Date: 21-Feb-2010

Camshaft Gear (Camshaft Installed) Procedure, Initial Check and Measure Section Additions

Camshaft Gear (Camshaft Installed) Procedure, Initial Check and Measure Section Additions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds Initial Check and Measure section to Procedure 001-012 (Camshaft Gear (Camshaft Installed)) in the K38, K50, QSK38, and QSK50 Service Manual, Bulletin 4021528.

Related Procedures

28-001-012-tr
(/qs3/pubsys2/xml/en/procedures/28/28-001-012-tr.html)

Camshaft Gear (Camshaft Installed)
(/qs3/pubsys2/xml/en/procedures/28/28-001-012-tr.html)

Last Modified: 21-Feb-2010