



# Technical Service Bulletin

Technical Service Bulletin: tsb104027

Released Date: 08-Feb-2010

Cylinder Liner Procedure, Clean and Inspect for Reuse and Measure Section Revision;  
Piston Rings Procedure, Measure Section Revision

## Cylinder Liner Procedure, Clean and Inspect for Reuse and Measure Section Revision; Piston Rings Procedure, Measure Section Revision

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Service/Parts Topic revises Procedures 001-028 (Cylinder Liner) and 001-047 (Piston Rings). A new top piston ring resulted in the piston ring gap clearances being different than the original ring. The modifications to the piston rings include new details of the new clearance, as well as introduce a specific region on the liner bore which will be used for this measurement. The changes to the cylinder liner procedure are associated with the piston ring procedure in that it asks for the cylinder liner to be measured in the same region as the piston ring. It requires the diameter at this point to be recorded so it can be used to assist in the assessment of the piston ring gap in the piston ring procedure.

Procedure 001-028 (Cylinder Liner), Measure Section, used in the Engine Assembly Section of Bulletin 4021528, did **not** include a section on how to measure the cylinder liner protrusion. A link has been placed at the end of the Measure Section, directing users to Procedure 001-064 (Cylinder Liner Protrusion).

### Related Procedures

|                                                                                 |                                                                              |
|---------------------------------------------------------------------------------|------------------------------------------------------------------------------|
| 28-001-028-tr<br>(/qs3/pubsys2/xml/en/procedures/28/28-001-028-tr.html)         | Cylinder Liner<br>(/qs3/pubsys2/xml/en/procedures/28/28-001-028-tr.html)     |
| 28-001-028-shopas<br>(/qs3/pubsys2/xml/en/procedures/28/28-001-028-shopas.html) | Cylinder Liner<br>(/qs3/pubsys2/xml/en/procedures/28/28-001-028-shopas.html) |

28-001-047-tr  
(/qs3/pubsys2/xml/en/procedures/28/28-001-047-tr.html)

Piston Rings  
(/qs3/pubsys2/xml/en/procedures/28/28-001-047-tr.html)

---

**Last Modified: 08-Feb-2010**

---