



Technical Service Bulletin

Technical Service Bulletin: TSB110153

Released Date: 01-Jun-2011

INSITE™ Engine Abuse History Usage

INSITE™ Engine Abuse History Usage

Core Issue

INSITE™ electronic service tool Engine Abuse History parameter “Engine Oil Pressure” should **not** be used as a basis for warranty claim consideration.

When a claim or an issue comes in related to engine usage, repair, or warranty; technicians evaluating the situation should **not** consider the parameter “Engine Oil Pressure” in the Engine Abuse History feature in INSITE™ electronic service tool as a basis of determining the root cause of an issue. The time in these severity states is misleading and does **not** represent the true state of Engine Oil Pressure, since it measures starting from the key ON state. This time will accumulate in the Severity 3 category with every key ON and could lead a technician to conclude the engine spent what falsely appears to be an excessive amount of time in a severe Engine Oil Pressure state.

Confirmation

N/A

Resolution

Technicians should first determine if there was an Engine Oil Pressure issue using INSITE Engine Protection. This feature records the faults that cause derate conditions. The fault codes related to severe Engine Oil Pressure issue are 0415 and 0143. A technician can expand these faults and view the number of times the fault occurred and how much time was spent in each occurrence.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2011-5-13	Module Created

Last Modified: 01-Jun-2011