



Technical Service Bulletin

Technical Service Bulletin: TSB120093

Released Date: 09-Apr-2012

New High-Pressure Injector Supply Lines for MCRS Engines

New High-Pressure Injector Supply Lines for MCRS Engines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces new high-pressure injector supply lines for the QSK19 MCRS, QSK38 MCRS, QSK50 MCRS, and QSK60 MCRS engines with electronically actuated injectors. The new lines are more resistant to water, dirt, and debris intrusion through the grommet.

New and Old High-Pressure Injector Supply Line Information

New Part Number	Old Part Number	Engine	Application	Location Description	Plant Implementation Date
2896819	4918081	QSK19	Construction & PowerGen	Pump to Injector	23-Jan-2012
2896821	4924231	QSK19	Construction, PowerGen & Marine	Injector to Injector	23-Jan-2012
2896823	4924626	QSK38/50/60	Construction, PowerGen & Marine	Injector to Injector	20-Feb-2012
2896825	4924630	QSK60	Construction, PowerGen & Marine	Pump to LB Injector	20-Feb-2012
2896827	4924634	QSK60	Construction & PowerGen	Pump to RB Junction	20-Feb-2012
2896831	4927491	QSK38/50	Construction, PowerGen & Marine	Pump to LB Injector	20-Feb-2012

New and Old High-Pressure Injector Supply Line Information					
New Part Number	Old Part Number	Engine	Application	Location Description	Plant Implementation Date
2896833	4927495	QSK38/50	Construction, PowerGen & Marine	Pump to RB Junction	20-Feb-2012
2896835	4927499	QSK38/50	Construction, PowerGen & Marine	RB Junction	20-Feb-2012
2896837	4956285	QSK38/50	Marine	RB Junction	20-Feb-2012
2896911	4956288	QSK38/50	Marine	Pump to RB Junction	20-Feb-2012
2896913	4956294	QSK38/50	Marine	RB Junction to Injector	20-Feb-2012
2896916	4970128	QSK19	Marine	Pump to Injector	23-Jan-2012
2896918	4970865	QSK60	Marine	Pump to RB Junction	20-Feb-2012

Reference to the Clean and Inspect for Reuse section of Procedure 006-051 if any corrosion, dirt, or debris, is found on injector supply lines.

Document History

Date	Details
2012-3-29	Module Created

Last Modified: 09-Apr-2012
