



Technical Service Bulletin

Technical Service Bulletin: TSB120289

Released Date: 21-Dec-2012

QST30 Industrial Calibration Revision: Fault Codes 299, 423, 772, 773, and 611

QST30 Industrial Calibration Revision: Fault Codes 299, 423, 772, 773, and 611

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces a update in the Calibration Software Phase to 5.1.0.5 for QST30 Industrial engines. The calibration change was made to alter the logic for Fault Codes 423, 772, and 773. The calibration also added Fault Codes 299 and 611.

Fault Codes 772 and 773 are for the needle lift sensor for the left and right bank reading **not** being detected or out of range.

Fault Codes 772 and 773 will no longer display a lamp but will be logged in the engine control module (ECM). The lamp strategy of the revised calibrations meets Cummins® Engineering Standards.

Fault Code 423 is caused by incorrect static pump timing, clogged fuel filters or inlet screen, a stuck timing sleeve, air in the fuel lines, or calibration errors. The logic was revised to make the fault code more robust to signal noise.

Fault Codes 299 and 611 were added to these calibrations. Fault Code 299 is for a non-keyswitch hot shutdown, which occurs when the engine is shutdown without the keyswitch when the engine did **not** have time to cool down properly. Fault Code 611 will trigger when the engine was shut down without allowing the proper cool down.

Engines built on or after 19 November 2012 have the updated 5.1.0.5 Calibration Software Phase.

The new calibrations were installed in production engines built on or after 19 November 2012

Table 1: Previous and Revised Calibrations

Previous Calibration	Revised Calibration
K50176.03	K50176.04
K50186.01	K50186.02
K50187.01	K50187.02

Table 1: Previous and Revised Calibrations	
K50017.22	K50017.23
K50024.23	K50024.24
K50043.21	K50043.22
K50054.20	K50054.21
K50055.18	K50055.19
K50057.15	K50057.16
K50059.13	K50059.14
K50061.11	K50061.12
K50061.16	K50061.17
K50063.14	K50063.15
K50065.14	K50065.15
K50066.13	K50066.14
K50067.12	K50067.13
K50069.14	K50069.15
K50070.11	K50070.12
K50071.11	K50071.12
K50072.05	K50072.06
K50072.10	K50072.11
K50073.05	K50073.06
K50073.10	K50073.11
K50076.10	K50076.11
K50077.05	K50077.06
K50077.10	K50077.11
K50082.11	K50082.12
K50083.10	K50083.11
K50084.09	K50084.10
K50085.10	K50085.11
K50088.08	K50088.09
K50092.03	K50092.04
K50092.08	K50092.08
K50093.03	K50093.04
K50093.07	K50093.08
K50094.03	K50094.04
K50094.08	K50094.09
K50103.03	K50103.04
K50123.03	K50123.04

Table 1: Previous and Revised Calibrations	
K50126.02	K50126.03
K50137.01	K50137.02
K50180.01	K50180.02
K50074.11	K50074.12
K50075.12	K50075.13
K50078.10	K50078.11
K50086.08	K50086.09
K50089.08	K50089.09
K50090.07	K50090.08
K50091.08	K50091.09
K50095.08	K50095.09
K50096.09	K50096.10
K50097.10	K50097.11
K50098.04	K50098.05
K50099.04	K50099.05
K50101.04	K50101.05
K50105.03	K50105.04
K50106.05	K50106.06
K50110.03	K50110.03
K50118.02	K50118.03
K50131.02	K50131.03
K50133.02	K50133.03
K50136.02	K50136.03
K50164.01	K50164.02
K50183.02	K50183.03
K50028.20	K50028.21
K50062.11	K50062.12
K50064.10	K50064.11
K50068.07	K50068.08
K50080.06	K50080.07
K50081.07	K50081.08
K50087.05	K50087.06
K50100.04	K50100.05
K50102.04	K50102.05
K50104.02	K50104.03
K50113.01	K50113.02

Table 1: Previous and Revised Calibrations	
K50130.02	K50130.03
K50167.03	K50167.04
K50024.31	K50024.32
K50045.23	K50045.24
K50141.01	K50141.02
K50142.01	K50142.02
K50143.02	K50143.03
K50144.01	K50144.02
K50145.01	K50145.02
K50146.01	K50146.02
K50147.02	K50147.03
K50148.01	K50148.02
K50149.01	K50149.02
K50150.03	K50150.04
K50151.01	K50151.02
K50152.01	K50152.02
K50153.01	K50153.02
K50154.01	K50154.02
K50155.02	K50155.03
K50156.02	K50156.03
K50157.01	K50157.02
K50158.01	K50158.02
K50159.01	K50159.02
K50162.01	K50162.02
K50163.01	K50163.02
K50166.01	K50166.02
K50171.01	K50171.02
K50172.01	K50172.02
K50173.02	K50173.03
K50174.02	K50174.03
K50175.01	K50175.02
K50177.02	K50177.03
K50178.01	K50178.02
K50179.01	K50179.02
K50181.01	K50181.02
K50182.01	K50182.02

Table 1: Previous and Revised Calibrations	
K50161.03	K50161.04
K50014.21	K50014.22
K50132.02	K50132.03
K50160.01	K50160.02
K50139.02	K50139.03
K50140.02	K50140.03
K50165.01	K50165.02
K50169.01	K50169.02
K50170.01	K50170.02
K50188.01	K50188.02
K50189.01	K50189.02

Document History

Date	Details
2012-11-15	Module Created

Last Modified: 21-Dec-2012
