



Technical Service Bulletin

Technical Service Bulletin: TSB130132

Released Date: 05-Sep-2013

New Exhaust Gas Temperature Sensor for QSK38 and QSK50 Tier 2 Engines

New Exhaust Gas Temperature Sensor for QSK38 and QSK50 Tier 2 Engines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of a revised exhaust gas temperature sensor for use in the QSK38 and QSK50 Tier 2 engines.

The revised exhaust gas temperature sensor was released to improve durability of the sensor and its wiring system. Changes to the sensor include a longer sensor body housing.

This part is released for service only. An announcement will be released when these parts are implemented into production.

Parts will be available from the 30 Sept 2013 to order from Cummins® parts distribution centers.

Table 1: New Exhaust Gas Temperature Sensor Numbers

Description	New Part Number	Old Part Number
Exhaust Gas Temperature Sensor	4326918	4954490

Use the following procedure for more information on removal and installation of the exhaust gas temperature sensor in the K38 and K50 CENSE™ Electronic Control System Troubleshooting and Repair Manual, Bulletin 4022102. Refer to Procedure 019-013 in Section 19.

(/qs3/pubsys2/xml/en/procedures/122/122-019-013.html)

Document History

Date	Details
2013-8-28	Module Created

