



Technical Service Bulletin

Technical Service Bulletin: TSB150140

Released Date: 22-Sep-2015

New Engine Interface Harness for Mining Applications

New Engine Interface Harness for Mining Applications

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM552 (Mining applications in India **only**)

Description of Change

This document introduces a new engine interface harness. The new fully braided engine interface harness is more robust and better able to operate in the mining application environment. The new engine interface harness is supplied by Cummins Inc. but installed by the OEM.

Reason for Change

The new engine interface harness wiring material is more durable and has better heat resistant properties that can withstand temperatures of up to 180°C [356°F].

Service Parts Availability

Table 1, Service Parts

Part Description	Obsolete Part Number	New Part Number
Engine Interface Harness	4987348	4346201

Part Structure

Existing engine interface harness, Part Number 4987348, has been obsoleted and superseded by new engine interface harness, Part Number 4346201.

Part Compatibility

The new engine interface harness is compatible with Murphy® panels.

Production Status

Table 2, Production Information		
ESN First	Build Date*	Plant
37246455	20 October 2010	Cummins Industrial Center
*Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2015-8-18	Module Created

Last Modified: 22-Sep-2015
