



Technical Service Bulletin

Technical Service Bulletin: TSB150154

Released Date: 04-Oct-2018

INSITE™ Electronic Service Tool Engine Oil Pressure Values Will Not Change In the Data Monitor/Logger

INSITE™ Electronic Service Tool Engine Oil Pressure Values Will Not Change In the Data Monitor/Logger

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Issue

In INSITE™ electronic service tool version 8.1.1.199, while trying to monitor or data log engine oil pressure in data monitor/logger during engine operation, the oil pressure value will **not** change.

Resolution

A temporary solution is to install INSITE™ electronic service tool version 8.0.3.142.

INSITE™ electronic service tool version 8.0.3.142 can be downloaded using the link below.

Note : <https://www.cummins.com/support/electronic-service-tools-support/insite-support> (<https://www.cummins.com/support/electronic-service-tools-support/insite-support>)

A permanent fix is being developed and will be released with INSITE™ electronic service tool version 8.1.1 service pack 1.

Document History

Date	Details
2015-9-18	Module Created
2018-10-4	Corrected URL

Last Modified: 04-Oct-2018

