



Technical Service Bulletin

Technical Service Bulletin: TSB150183

Released Date: 04-Oct-2018

INSITE™ Electronic Service Tool Technical Support

INSITE™ Electronic Service Tool Technical Support

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- All engines that use INSITE™ electronic service tool

Service Instructions

This document clarifies the correct way to report any technical issues that may occur with INSITE™ electronic service tool.

If technical support is required with Cummins INSITE™ electronic service tool, visit <http://care.cummins.com> using the link below.

Note : <https://insite.cummins.com/insite/index.html>
(<https://insite.cummins.com/insite/index.html>)

Technical support can be provided by the following methods:

- Telephone
 - Click on the phone support link to access regional assistance information.
- Email
 - Email addresses are also shown when clicking on the phone support link.
- Live Chat
 - Access to Cummins® intranet or internet access required, as the supporting INSITE™ technician may need to remotely connect to the computer with the issue.

The following information will be required when requesting INSITE™ electronic service tool technical support:

- Computer operating system (Windows 8.X, Windows 10.X)
- Version of INSITE™ electronic service tool software installed (Open INSITE™ electronic service tool, click on 'Help' and open 'About INSITE'). See Figure 1.
- Type of INLINE datalink adapter used.
 - INLINE datalink adapter model (INLINE 5, INLINE 6).
 - INLINE datalink adapter serial number (Printed on label on rear of datalink adapter).

- INLINE datalink adapter firmware installed (The firmware version is shown at the top of the INSITE™ electronic service tool screen after a connection has been made). See Figure 2.

- Connection type (J1939, USB or Serial)
- Any error code numbers that may have been displayed at the time of the problem occurring.
- Engine model
- Electronic control module (ECM) type and ECM calibration version (for all engine ECMs).
- A concise and accurate description of the problem. If emailing a request for technical support, ECM image files and screen shots will be required.

Customer Communication

Cummins® distributors and dealers should share this document with all self-servicing customers.

Service Tools and Training Available

INSITE™ electronic service tool updates, datalink support and information, and electronic service tools training material can also be accessed at <http://care.cummins.com>




Figure 1, About INSITE




Figure 2, Firmware Version Location

Document History

Date	Details
2015-11-19	Module Created
2018-10-4	Corrected URL

Last Modified: 04-Oct-2018
