



Technical Service Bulletin

Technical Service Bulletin: TSB160036

Released Date: 10-Feb-2020

New Centrifuge Cover, Eliminator™ Assembly, and Centrifugal Filter for Eliminator™ Oil Filters

New Centrifuge Cover, Eliminator™ Assembly, and Centrifugal Filter for Eliminator™ Oil Filters

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK38 CM850
- QSK38 CM2150
- QSK38 CM2150 K106
- QSK45 CM500
- QSK45G Natural Gas
- QSK50 CM850
- QSK50 CM2150
- QSK50 CM2150 K107
- QSK50 CM2350 K108
- QSK60 CM2150 MCRS
- QSK60 CM2250 K112
- QSK60 CM2358
- QSK60 CM500
- QSK60 CM850 MCRS
- QSK60 G CM2358 K110
- QSK60 G Natural Gas
- QSK78 Construction CM500
- QSK78 Locomotive CM500

Natural Gas – with Natural Gas Fuel System

Description of Change

A new centrifugal filter has been introduced for the Eliminator™ filter system. The casting tolerance of the new centrifuge cover has been adjusted and a new complete Eliminator™ assembly part number has been introduced to reflect these changes.

Reason for Change

The new centrifugal filter will prevent lower bushing malfunctions. The centrifuge cover has been changed to allow the new centrifuge filter to be used without contacting the centrifuge cover during engine operation.

Service Instructions

- If evidence of contact between the centrifuge cover and centrifuge filter is found, the centrifuge cover, Part Number 4016423 (QSK78 centrifuge cover), can be purchased separately and installed within the existing Eliminator™ assembly to prevent centrifuge filter contact with the centrifuge cover. Applicable to QSK45/60. See Figure 1 below.
- For installation and removal, see Service Bulletin, Eliminator™ Filter, Bulletin 3666253 (/qs3/pubsys2/xml/en/bulletin/3666253.html).

©Cummins Inc



Figure 1, Evidence of Contact Between Centrifuge Cover and Centrifuge Filter.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Service Parts					
Part Description	Existing Part Number	Obsoleted	Superseded	New Part Number	SpiraTec™ Reference number

QSK60 Filter, Lubricating Oil (Eliminator™ Assembly)	3649418	Yes	Yes	5540796	Not Applicable
QSK45 Filter, Lubricating Oil (Eliminator™ Assembly)	3649420	Yes	Yes	5540797	
QSK78 Filter, Lubricating Oil (Eliminator™ Assembly)	3649552	Yes	Yes	5540795	
Cover, Centrifuge	Not Applicable			4016423	
Filter, Centrifuge (QSK45/60)				4331734	CS41018
Filter, Centrifuge (QSK78)	Not Applicable			5538318	CS41019
QSK38/50 Filter, Lubricating Oil (Eliminator™ Assembly) With Filling tube	Not Applicable			5540856	Not Applicable
QSK38/50 Without Filling tube Filter, Lubricating Oil (Eliminator™ Assembly)	Not Applicable			5540857	Not Applicable

Part Compatibility

The new part numbers are backwards compatible and can be mixed with existing part numbers.

Note : If the one-piece centrifuge is fitted to an engine that has previously had a restrictor orifice fitted to the centrifuge shaft, the restrictor must be removed. It can be removed from the shaft with a hex key.

Recommendation

Replace the centrifuge every 1000 hours with at least one inspection interval after 500 hours to assess bush wear if present.

Part Identification

The new cover can be identified by 'V' on the side of the housing. See Figure 2.

©Cummins Inc



Figure 2, Identification Mark on Centrifuge Housing.

Production Status

Table 2, Production Information			
Product	Engine Serial Number (ESN) First	Build Date ¹	Engine Plant
QSK60	33207365	06 May 2016	Daventry Engine Plant
¹ Engine build date can be found on the engine dataplate.			

Document History

Date	Details
2016-4-11	Module Created
2016-6-13	Updated Product Affected list and Table 1. Added ESN first and build date.
2017-5-3	Note added to Part Compatibility Section.
2020-1-7	Added QSK78 part numbers.
2020-2-10	Updated Product Affected list and added necessary products to metadata.

Last Modified: 10-Feb-2020
