



Technical Service Bulletin: TSB160067

Released Date: 04-Oct-2018

INSITE™ Electronic Service Tool and Engine Control Module (ECM) Calibration Security Changes

INSITE™ Electronic Service Tool and Engine Control Module (ECM) Calibration Security Changes

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- All products supported by INSITE™ electronic service tool

Description of Change

INSITE™ electronic service tool version 8.1.4 has an improved level of security for engine control module (ECM) calibrations. These security changes in INSITE™ are aligned with security changes in all upcoming Cummins® ECM calibrations. These security changes **only** affect the ECM calibration download capability of INSITE™ Pro and Road Speed Governor Restricted (RSGR)/Industrial Pro™ version 8.1.4.

Reason for Change

This improved security is intended to make certain **only** authentic Cummins® ECM calibrations are downloaded into electronic control modules and programmable datalink devices.

Customer Communication

Beginning 26 July 2016, INSITE™ Pro version 8.1.4 will be needed for all ECM calibrations released on 26 July 2016 and thereafter. This free update will be pushed to all licensed users of INSITE™ Pro. Older versions of INSITE™ Pro will **not** recognize ECM calibrations released after this date. Cummins Inc. recommends updating to the existing version of INSITE™ Pro (8.1.3) now so updates beginning on 26 July 2016 are **not** as time consuming. This update will provide the option to delay the install up to three times before commencing with an automatic update.

INSITE™ users will be notified through an automated pop-up window when INSITE™ 8.1.4 is available for installation. For seamless customer support, Cummins Inc. recommends INSITE™ be updated to the new version when prompted.

Service Instructions

If INSITE™ is **not** updated, previous versions of INSITE™ will **only** download ECM calibrations on old INCAL™ DVDs that have **not** expired. Once INCAL™ DVDs have expired, INSITE™ will no longer be able to download any ECM calibration until updated to INSITE™ version 8.1.4.

Note : If issues are encountered with the INSITE™ update or ECM calibration process, call (800) 433-9341 and select option 2. The hotline will be operating 24 hours a day during this update period between 26 July 2016 and 15 August 2016.

Beginning July 26th, **only** these new ECM calibrations with improved embedded security will be available from QuickServe® Online (QSOL) and from the ECM Code Search and Save feature within INSITE™. Between 26 July 2016 and 15 August 2016, older versions of INSITE™ will still be able to download older ECM calibrations from the INCAL™ DVDs and <http://care.cummins.com>. However, INCAL™ DVDs will expire seven months after publication. The next release of INCAL™ DVD on 26 July 2016 will contain **only** the new ECM calibrations with improved embedded security and can **only** be downloaded with INSITE™ version 8.1.4.

Part Compatibility

Table 1, INSITE™ Electronic Service Tool Version and ECM Calibration Compatibility Chart: Before Embedded Security

ECM Calibration Source	QuickServe® Online and ECM Code Search	http://care.cummins.com	INCAL™ DVD
Date	Before 26 July 2016	Between 26 July 2016 and 15 August 2016	Before 26 July 2016
INSITE™ Version 8.1.4 and newer	-	-	Not Compatible
INSITE™ Version 8.1.3 and older	Compatible	Compatible	Compatible

Table 2, INSITE™ Electronic Service Tool Version and ECM Calibration Compatibility Chart: After Embedded Security

ECM Calibration Source	QuickServe® Online and ECM Code Search	http://care.cummins.com	INCAL™ DVD
Date	After 26 July 2016	After 15 August 2016	After 26 July 2016
INSITE™ Version 8.1.4 and newer	Compatible	-	Compatible
INSITE™ Version 8.1.3 and older	Not Compatible	-	Not Compatible

Document History

Date	Details
2016-7-1	Module Created
2018-10-4	Corrected URLs.

Last Modified: 04-Oct-2018
