



Technical Service Bulletin

Technical Service Bulletin: TSB180093

Released Date: 18-Mar-2020

Slow Inlet Metering Valve Fuel Pump Obseletion

Slow Inlet Metering Valve Fuel Pump Obseletion

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSKTA38
- QSKTA50
- QSKTA60
- QSKTA19

Description of Change

Slow inlet metering valve fuel pumps are no longer available for service, and are to be replaced with fast inlet metering valve fuel pumps. Engine control module (ECM) updates are necessary for this change, see tables below for corresponding fuel ratings according to application.

Reason for Change

Slow inlet metering valve fuel pumps are no longer available for service.

Customer Communication

Recommend upgrade **only** if a replacement is necessary.

Service Instructions

ECM calibration **must** be performed when replacing slow inlet metering valve fuel pump with fast inlet metering valve fuel pump. See application tables below for corresponding fuel rating options.

Note : Extension harness, Part Number 2881173, **must** be used when installing a fast IMV pump on a slow IMV engine to bridge the gap in the wiring harness.

Note : For Construction application, reference TSB130102

Application:

Table 1, QSK38 Marine				
Slow inlet metering valve ECM	Revision Number	Fast IMV ECM	Revision Number	Fuel Rating Option
AQ60042	11	AQ60873	00	FR6591
AQ60041	10	AQ60870	00	FR6592
AQ60028	11	AQ60871	00	FR6558
AQ60122	07	AQ60872	00	FR6668
AQ60082	04	AQ60869	00	FR6579
AQ60106	03	AQ60868	00	FR6637

Table 2, QSK50 Marine				
SLOW IMV ECM	Revision Number	Fast IMV ECM	Revision Number	Fuel Rating Option
AQ60046	13	AQ60852	00	FR6593
AQ60029	14	AQ60859	00	FR6575
AQ60123	11	AQ60850	00	FR6669
AQ60047	14	AQ60848	00	FR6594
AQ60107	4	AQ60854	00	FR6638
AQ60038	6	AQ60860	00	FR6580

Table 3, QSK60 Marine				
SLOW IMV ECM	Revision number	Fast IMV ECM	Revision number	Fuel Rating Option
AQ60058	04	AQ60856	00	FR6596
AQ60108	03	AQ60863	00	FR6650
AQ60109	03	AQ60849	00	FR6651
AQ60120	03	AQ60867	00	FR6663
AQ60121	03	AQ60851	00	FR6664
AQ60156	04	AQ60865	00	FR6652
AQ60157	04	AQ60866	00	FR6595
AQ60180	03	AQ60864	00	FR6720

Table 4, QSK38 Power Gen				
SLOW IMV ECM	Revision number	Fast IMV ECM	Revision number	Fuel Rating Option
AQ60185	04	AQ60842	00	FR6698
AQ60203	03	AQ60843	00	FR6701
AQ60201	03	AQ60844	00	FR6700
AQ60176	07	AQ60845	00	FR6697

Table 4, QSK38 Power Gen				
SLOW IMV ECM	Revision number	Fast IMV ECM	Revision number	Fuel Rating Option
AQ60187	05	AQ60846	00	FR6699
AQ60425	01	AQ60960	00	FR06964
AQ60497	00	AQ60959	00	FR60051

Table 5, QSK50 Power Gen				
SLOW IMV ECM	Revision number	Fast IMV ECM	Revision number	Fuel Rating Option
AQ60137	12	AQ60853	00	FR6643
AQ60138	10	AQ60853	00	FR6643
AQ60525	01	AQ60855	00	FR6622
AQ60143	11	AQ60857	00	FR6641
AQ60144	10	AQ60857	00	FR6641
AQ60153	11	AQ60858	00	FR6653
AQ60154	10	AQ60858	00	FR6653
AQ60072	10	AQ60861	00	FR6622
AQ60205	10	AQ60862	00	FR6726
AQ60206	06	AQ60862	00	FR6726
AQ60473	06	AQ60862	00	FR6726
AQ60102	11	AQ60963	00	FR6621
AQ60139	12	AQ60966	00	FR6654
AQ60140	10	AQ60966	00	FR6654
AQ60141	12	AQ60961	00	FR6655
AQ60142	10	AQ60961	00	FR6655
AQ60145	11	AQ60964	00	FR6642
AQ60146	10	AQ60964	00	FR6642
AQ60151	12	AQ60968	00	FR6667
AQ60152	10	AQ60968	00	FR6667
AQ60178	05	AQ60967	00	FR6692
AQ60179	05	AQ60962	00	FR6693
AQ60119	10	AQ60965	00	FR6661
AQ60074	06	AQ60974	01	FR6606
AQ60103	07	AQ60974	01	FR6606
AQ60100	07	AQ60974	01	FR6606

Table 6, QSK60 Power Gen				
SLOW IMV ECM	Revision number	Fast IMV ECM	Revision number	Fuel Rating Option
AQ60132	09	AQ60832	00	FR6670
AQ60133	09	AQ60832	00	FR6670
AQ60128	10	AQ60833	00	FR6665
AQ60129	10	AQ60833	00	FR6665
AQ60241	05	AQ60833	00	FR6665
AQ60164	07	AQ60834	00	FR6973
AQ60126	11	AQ60835	00	FR6645
AQ60127	10	AQ60835	00	FR6645
AQ60147	11	AQ60836	00	FR6646
AQ60148	11	AQ60836	00	FR6646
AQ60124	12	AQ60837	00	FR6644
AQ60125	11	AQ60837	00	FR6644
AQ60207	12	AQ60838	01	FR6671
AQ60418	01	AQ60839	00	FR6962
AQ60158	09	AQ60840	00	FR6682
AQ60159	09	AQ60840	00	FR6682
AQ60160	09	AQ60841	00	FR6683
AQ60161	09	AQ60841	00	FR6683
AQ60149	09	AQ60970	00	FR6647
AQ60150	09	AQ60970	00	FR6647
AQ60130	09	AQ60972	00	FR6666
AQ60131	09	AQ60972	00	FR6666
AQ60308	07	AQ60973	00	FR6845
AQ60419	01	AQ60971	00	FR6665

Table 7, QSK19 Power Gen				
Slow Inlet Metering Valve ECM	Revision Number	Fast IMV ECM	Revision Number	Fuel Rating Option
AQ40025	8	AQ40332	0	FR04446
AQ40026	8	AQ40332	0	FR04446
AQ40032	7	AQ40332	0	FR04446
AQ40030	7	AQ40331	0	FR04451
AQ40033	7	AQ40331	0	FR04451
AQ40035	7	AQ40331	0	FR04451

AQ40136	2	AQ40331	0	FR04451
Service Parts Availability				
Service parts are available. See Table 1 for part numbers.				
Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
FUEL PUMP	288874800NX	Yes	Yes	430651600NX
FUEL PUMP	288881000	Yes	Yes	430651500

Document History

Date	Details
2018-7-11	Module Created
2019-4-9	Added IMV harness note
2020-1-22	Non-Product Problem Solving (PPS)
2020-2-27	Non-Product Problem Solving (PPS)

Last Modified: 18-Mar-2020
