



Technical Service Bulletin

Technical Service Bulletin: TSB190044

Released Date: 14-Aug-2019

Connectivity Issues with INLINE™ 6 Datalink Adapter and Windows® 10 Version 1809 or Windows® 10 Version 1903

Connectivity Issues with INLINE™ 6 Datalink Adapter and Windows® 10 Version 1809 or Windows® 10 Version 1903

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Products Affected

- All electronically controlled engine products

Issue

Using a Windows® 10 Version 1809 or Windows 10 Version 1903 (sometimes called 19H1) operating system, when trying to connect INSITE™ electronic service tool using an INLINE™ 6 datalink adapter, intermittent connectivity issues can be observed.

Verification

To locate Windows® 10 Operating System build:

1. Press the Windows® Key and R key simultaneously to open Run dialog, then type winver and select OK. See Figure 1 below.




Figure 1, Run Dialog.

2. About Windows® dialog box will appear and provide the Windows® version and build details. See Figure 2 below.




Figure 2, Windows® Version.

Resolution

- New INLINE™ 6 drivers have been developed which will resolve this issue.
- Since the INLINE™ 6 drivers are still in field test, send an email to CumminsFieldTest@cummins.com with contact information (name, phone number, email address) and “INLINE 6 Drivers” in the Subject line, if interested in testing the INLINE 6 drivers.
- Additional Workaround: Use INSITE™ electronic service tool with INLINE™ 6 connecting through 9-pin serial port, or use another datalink adapter, such as an INLINE™ 7.
- To avoid any disruptions or download failures, using a computer with a different operating system and/or different version number and/or different datalink adapter for any ECM calibration code downloads is recommended.

Document History

Date	Details
2019-3-19	Module Created
2019-8-14	Added information about Windows 10 Version 1903.

Last Modified: 14-Aug-2019
