



Technical Service Bulletin

Technical Service Bulletin: TSB190191

Released Date: 19-May-2020

Microsoft Windows™ 7 Obsolescence for Electronic Service Tools

Microsoft Windows™ 7 Obsolescence for Electronic Service Tools

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- All electronically controlled engine products.

Issue

As of January 2020, Microsoft support has ended for Windows™ 7 SP1 and lower versions.

- Technical support for the INSITE™ electronic service tool may no longer be fully available when using Windows™ 7 SP1 and lower version operating systems.
- INSITE™ electronic service tool will no longer be supported for Microsoft Windows™ 7 upon release of version 8.6.2. on or after 09 July 2020.
- License Configuration Tool will no longer be supported for Microsoft Windows™ 7 on 15 July 2020.
- Cummins® Inc. Update Manager will no longer be supported for Microsoft Windows™ 7 on 20 December 2020.
- For Cummins® employees, Cummins® Inc. Update Manager will cease to function on computers with Microsoft Windows™ 7 on 20 December 2020.

Resolution

Upgrade to a supported Microsoft Windows™ version.

Document History

Date	Details
2019-11-8	Module Created
2020-2-12	Non-Product Problem Solving (PPS)

Date	Details
2020-2-17	Quick Fix application:
2020-5-19	Updated Cummins Inc. Update Manager will no longer be supported and cease to function on computers date.

Last Modified: 19-May-2020
