



Technical Service Bulletin

Technical Service Bulletin: TSB190192

Released Date: 11-Nov-2019

Updates to Engine Control Module (ECM) Calibration Code Security

Updates to Engine Control Module (ECM) Calibration Code Security

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Products Affected

- All electronically controlled engine products 2007 and newer.

Issue

New engine control module (ECM) calibration codes have been released using industry standard encryption for all electronically controlled engine products. These ECM calibration codes are **only** supported in INSITE™ electronic service tool version 8.6.0 and newer.

Resolution

If using an INCAL™ DVD with INSITE™ electronic service tool version 8.6.0, ECM calibration codes **must** be from December 2019 or newer. These new ECM calibration codes can also be downloaded from Quickserve® Online (QSOL) or ECM Code Search within INSITE™ electronic service tool. Any previous INCAL™ DVDs or downloaded ECM calibration codes will no longer be supported.

Document History

Date	Details
2019-11-8	Module Created

Last Modified: 11-Nov-2019