



Technical Service Bulletin

Technical Service Bulletin: TSB200247

Released Date: 04-Oct-2024

Changes to Engine Control Module (ECM) Calibration Code Security Requiring INSITE™
Electronic Service Tool Version 8.7.0 or Newer

Changes to Engine Control Module (ECM) Calibration Code Security Requiring INSITE™ Electronic Service Tool Version 8.7.0 or Newer

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Products Affected

- All electronically controlled engine products

Issue

On 10 December 2020, new engine control module (ECM) calibration codes will be released using industry standard encryption for all electronically controlled engine products. These ECM calibration codes are **only** supported in INSITE™ electronic service tool version 8.7.0 and newer. If users do **not** upgrade, users will **not** be able to use any ECM calibrations downloaded through QuickServe® Online (QSOL) or Cal over web after 10 December 2020.

Resolution

On 10 December 2020, new ECM calibrations will be released using new industry standard encryption. This will require use of INSITE 8.7.0 or greater when using these calibrations downloaded from Quickserve Online (QSOL) or using the ECM Code Search feature within INSITE™. Cummins Inc. recommends users upgrade to INSITE 8.7.0 as soon as possible. Calibrations released after December 2019 or on an INCAL™ DVD from August 2020 or later can still be used with INSITE 8.7.0.

1. During the installation of the INSITE 8.7.0.exe, the user might see multiple dialog boxes of antivirus detecting suspicious files during the whole installation. The user does **not** need to acknowledge them.




Figure 1, Example of Antivirus Dialog Box.

2. If a user wants to use the INSITE 8.7.0 Other Package, the extracted other package can **only** be used once. If user wants to use is a second time, the user needs to delete the extracted package and re-extract the OtherPackage.zip file.

Document History

Date	Details
2020-12-14	Module Created
2024-10-4	Checking TSB's contents.